

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only, T23-3

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by James P. Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol. 5 Page(s) 2169-70)

Set a post 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 25, 30, 31 and 36, marked T23S S30 on NE.; R2W S31 on SE.; R3W S36 on SW.; and S25 on NW. faces, with 5 notches on the N. and 1 notch on S. face, from which

- A Hemlock 20" dia., bears N.15°E., 66 lks. dist. mkd. T23S R2W S30 BT.
- A Spruce 40" dia., bears S.80°E., 13 lks. dist. mkd. T23S R2W S31 BT.
- A Hemlock 10" dia., bears S.85°W., 16 lks. dist. mkd. T23S R3W S36 BT.
- A Hemlock 30" dia., bears N.15°W., 39 lks. dist. mkd. T23S R3W S25 BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2186)

(Chandler found and tied above corner then- - -" I destroyed the marks referring to Secs. 30 and 31."

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 2, 1967 - C.S. File 54/16-27

Found 1½" I.P. for cor. and marked pipe, 8 ft. above ground and BTs. Weyerhaeuser method as follows:
OBT, 10" now 16" Hemlock S.75°W., 10.5 ft., now stump and possibly out of position, scribe marks visible.
50" Fir stump S.74°E., 11.0 ft. "W" nail gone. Tag remains
No trace of other original BTs.
Nothing available for new BTs.
Corner lies 50 ft. East of road junction on ridge top on spur 4560.