

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2204)

Set a post 4 ft. long 4" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ on W face from which

- A Fir, 50" dia., bears S.85°W., 31 lks., mkd: ¼ S BT.
- A Fir, 16" dia., bears N.2°E., 16 lks., mkd: ¼ S BT.

Weyerhaeuser Co. 1958 thru 1963 C.S. File 53/106-6

Found - 50" Fir S.85°W., 31 lks., face evident, not chopped out, Doug. Co. Plate Cruiser's mark.

- 16" Fir N.2°E., 16 lks., tree rotted off level with ground, found scribing on fragments left at stump.

Set - Vine Maple stake, Sept 18, 1957

- 54" Orig. Fir BT N.81°W., 20.1 ft. "W" nail & plate.
- 46" Fir S.25°E., 22.4 ft., "W" nail & plate.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - July 1969 - C.S. File 54/27-110

Fd. Ok - Stake now ½" monel pipe at cor.

Glen McChesney - For: Weyerhaeuser Co. - Oct. 18, 1978 (Filed 6/1981) C.S. File 58/8-2

"MD Hale noted a discrepancy in the bearing to the 50" Fir BT as being N.81°W., instead of S.85°W., after determining the corner point by distances and noting the bearing NE BT as being good. After determining the corner point from Hale's called distances & bearings, I concur with his findings, except I have N.79°W., instead of N.81°W., to the orig. 50" Fir BT" Under all accessories I have driven round "W" nails beside Hale's square ones, put new plates on his reference trees (now stumps), changing the one to read N.79°w., instead of N.81°W., and have added the one new reference:

- A 24" Fir stump, bears N.38°E., 12.5 ft. with "W: nail & plate.