

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2207)

Set a basalt stone, 14x6x6 ins., 10 ins., in the ground for 1/4 sec. cor., mkd: 1/4 on W. face; from which
A Hemlock, 15" dia., bears S.57 1/2°E., 33 lks., mkd: 1/4 S BT.
A Hemlock, 8" dia., bears N.70°W., 33 lks., mkd: 1/4 S BT.

BLM, Eugene District Office, Party Chief: Ronald Van Domelen - Spring 1967 - C.S. File 53/106-4

Found - 2 stones of approx. size out of place. Could find no marks, possible due to being muddy.
Orig. 15" Hemlock, S.57 1/2°E., 33 lks., standing, visible scribe.
Orig. 8" Hemlock N.70°W., 33 lks., standing, visible scribe.

The trees were opposing and the distances overlapped. Set 2x2" stake using horizontal distance from NW BT & slope distance from SE BT. These distances matched reasonably well at the proper bearing. It was not possible to measure horizontal distance from the SE BT, but was easily done from the NW BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1969 - C.S. File 54/27-116

Found - Orig. 15" now 30" Hemlock, alive, N.57 1/2°E., 21.8 ft., scribed visible on open blaze. We rescribe "1/4 S29 DCS BT"

No trace of other OBT.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R2W OFFICE 1969 1/4 S29|S 30
New BT - 8" Hemlock N.65°W., 44.2 ft. mkd: "1/4 S30 DCS BT"

This corner is on E-W Lane - Douglas Co. Line on very steep westerly slope 40 ft. west of 15' high bluff.

NOTE - Wrong location, reset brass cap in proper location 10/1970

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - Oct. 1970 - C.S. File 54/27-116

Found - 1969 County Surveyor brass cap set in wrong position 15" now 30" Hemlock, alive, S.57 1/2°E., 21.8 ft., scribe still visible in hole on SW side of tree.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Reset brass cap in proper position from OBT.
Hemlock BT from 1969, now destroyed by recent logging.
No trees available, we scribe "W" reference stump as follows:
28" D.Fir stump S.82°W., 37.9 ft., to "W: nail mkd: "¼ S30
DCS BT"
OBT 30" Hemlock S.57½°E., 21.8 ft. (21.0 ft.) to "W" nail,
our rescribe on SW side OK "¼ S29 DSC BT"
The 1969 renewal should be disregarded, also NW OBT uncovered
by recent logging, down & out of position.

Robert Cook, Northstar Surveying Inc. - For: Weyerhaeuser Co.
- 10/2012 - C.S. File 65/91-4 - downloaded from Lane Co &
file with DCSO 1/21/2016

Found - 2½" Douglas Co. brass cap up 8" at end of cat road
from east per Douglas Co. (records) Steel post is
south 1'
28" D.Fir, stump S.85°30'W., 37.1 ft with tag and
paint.
20" Hemlock snag S.54°E., 21.1 ft., no marks.
BTs set- 16" D.Fir N.21°E. 16.3 ft scribed "¼ S29" above "BT"
20" D.Fir S.52°W. 17.2 ft scribed "¼ S30" above "BT"

Dan Baker - For: Weyerhaeuser Co. - Nov. 2015 - M170-28

Found - 2½" Douglas Co. brass cap "1970"
17" Fir N.20°E., 16.4' to center - 2012 Northstar BT
20" Hemlock snag, S.56°E., 21.1' to center, orig. BT
28" Fir stump, S.84°W., 37.2' to center, 1970
Douglas Co. BT.
21" Fir, S.51°W., 17.2' to center, 2012 Northstar BT
New - 18" Fir, S.9°E., 8.2' to center-scribed "¼ S29 BT"
10" Fir, N.20°W., 4.5' to center-scribed "¼ S30 BT"

Please note that this corner is on the Douglas Co. & Lane Co.
line and Lane Co. Surveyor's Office may have more information
concerning this corner.