

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under contract #438, dated May 3, 1882 - (DCSO records Vol. 6 Page(s) 2231)

A Hemlock 6" dia., which I mark ¼ S on W face for ¼ sec. cor. from which

- A Fir, 50" dia., bears South, 12 lks., mkd: ¼ S BT.
- A Fir, 60" dia., bears N.20°E., 25 lks., mkd: ¼ S BT.

Weyerhaeuser Co. 1957 thru 1963 C.S. File 53/107-20 (Jan. 1958)

Found - 6" Hemlock, now 15" broken off near ground level by logging, burnt & no scribing visible but I saw this in April 1956, when area was felled & bucked timber, & scribing was visible.

Set - 1"x2" Cedar stake in broken off Hemlock
60" burned out fir snap stump, possible OBT, S.31°W., 8.0 ft., no scribing visible or evident.
60" Fir N.20°E., 25.0 ft. Tree gone, hole in ground.

BTs - 28" Cedar stump N.73½°E., 30.8 ft. (OBT) "W" Nail & Plate.
48" Fir stump N.3°W., 26.0 ft. "W" Nail & Plate.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Nov. 1967 - C.S. File 54/16-51A

Since this corner was recorded (Jan. 1958) a ½" I. pipe has been set on E. side of Orig. corner stump & 1"x4' marker pipe. No trees avail. for new BT. "W" stumps in good condition