

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2442)

Set Cedar post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Dogwood 4" dia., bears N.21°E., 37 lks. dist. mkd. 1/4 S BT.
A Fir 20" dia., bears S.16°W., 72 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12704)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 26" in the ground, with brass cap mkd:
T23SR6W
1/4 S 30
S 31
1957

from which
A Fir 13" dia., bears N.26°W., 60 lks. dist. mkd. 1/4 S30 BT
A Fir 18" dia., bears South, 43 lks. dist. mkd. 1/4 S31 BT.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #244, Surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13504)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the 1/4 sec. cor. of secs. 30 and 31, erroneously reestablished by Eggen in 1957, bears S.39°25'W., 0.36 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the bearing trees, and at the corner point
Reset the iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked: T 23 S R 6 W
1/4 S 30
S 31
1957

from which new bearing trees
A Fir 8" dia., bears N.1°W., 47 lks. dist. mkd. 1/4 S30 BT
A Fir 25" dia., bears S.7°W., 58 lks. dist. mkd. 1/4 S31 BT

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19501)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T23S R6W
¼ $\frac{S\ 30}{S\ 31}$
1994

from which bearing trees mkd. by Brooks
A fir, 29 ins. diam., bears S. 53° W., 78 lks. dist., with healed blaze.

A fir, 12 ins. diam., bears N. 44½° W., 82 lks. dist., with healed blaze.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the ¼ sec. cor. of secs. 30 and 31, erroneously corrected by Brooks in 1964, bears N. 80° 09' 00" W., 0.561 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 2 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.

FD. Ok by D. Edwards, May 2005 - M147-56