

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2445)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Fir 8" dia., bears N.22°W., 83 lks. dist. mkd. ¼ S BT.
A Fir 20" dia., bears S.73°W., 109 lks. dist. mkd. ¼ S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12706)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 26" in the ground, with brass cap mkd:
T23SR6W
¼ $\frac{S\ 19}{S\ 30}$
1957

from which
A Fir 11" dia., bears N.56°E., 32 lks. dist. mkd. ¼ S19 BT
A Fir 11" dia., bears S.18°E., 53 lks. dist. mkd. ¼ S30 BT

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19504-05)

Point for the ¼ sec. cor. proportionate distance. There is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
T23S R6W
¼ $\frac{S19}{S30}$
1994

from which bearing trees mkd. by Gould, Gawron, and Eggen
A fir, 30 ins. diam., bears N. 36½° E., 55½ lks. dist., with healed blaze.
A fir, 30 ins. diam., bears S. 46° E., 30 lks. dist., with healed blaze.
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

From this point, the $\frac{1}{4}$ sec. cor. of secs. 19 and 30, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N. $15^{\circ} 12' 00''$ E., 0.286 chs. dist.; monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 8 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.

FD. Ok by D. Edwards, May 2005 - M147-56

Ronald L Rice - For: Roseburg Resources - Dec. 2015 - M170-39

Found - BLM brass cap dated 1994
37" W.Fir bears N. $36\frac{1}{2}^{\circ}$ E., 36.6', healed face.
30" W.Fir bears S. 46° E., 19.8', healed face.
 $2\frac{1}{2}$ " inverted iron pipe monument bears N. $15^{\circ}12'00''$ E.,
18.88', set below ground
New BT - 20" D.Fir bears N. 31° W., 21.4', blazed, scribed $\frac{1}{4}$
S19 BT
Steel post adjacent to corner.