

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2440)

-----  
Set Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on W. face, from which  
A Cedar 16" dia., bears N.60°E., 49 lks. dist. mkd. ¼ S BT  
A Fir 30" dia., bears N.55°W., 75 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12701-02)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 30" long, 2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:  
T23SR6W  
¼  
S31\*S32  
1957

from which  
A Fir 12" dia., bears N.74½°E., 44 lks. mkd. ¼ S32 BT  
A Fir 24" dia., bears N.73°W., 45 lks. dist. mkd. ¼ S31 BT

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #244, Surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13501-02)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
From this point, the ¼ sec. cor. of secs. 31 and 32, erroneously reestablished by Eggen, in 1957, bears West, 0.08 chs. dist., set, marked, and witnessed as described in the official record. I remove the iron post, and at the above corner point  
Reset the iron post, 28" long, 2½" dia., 27" in the ground, with brass cap mkd: T 23 S R 6 W  
¼  
S 31\*S 32  
1957

from which bearing trees mkd. by Eggen in 1957  
A Fir 15" dia., bears N.71°E., 36 lks. dist., with a healed blaze.  
A Fir 25" dia., bears N.76°W., 52 lks. dist., with a healed blaze.

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19499)

-----  
Point for the 1/4 sec. cor. at proportionate distance. There is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T23S R6W

1/4

S31 \* S32

1994

from which bearing trees mkd. by Gould, Gawron, and Eggen  
A fir, 20 ins. diam., bears N. 73° E., 78 lks. dist., with healed blaze.

A fir, 36 ins. diam., bears N. 21° W., 25 lks. dist., with healed blaze.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

The corner is located at head of ravine, drains NE.

From this point, the 1/4 sec. cor. of secs. 31 and 32, erroneously corrected by Brooks in 1964, bears N. 76° 05' 30" E., 0.429 chs. dist.; monumented with an iron post, 2 ins. diam., firmly set flush with the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.

Robert Ward - Ron Rice & Josh Reed, crew - June 2010 - C.S. File 65/69-31 & C.S. File 65/81-14 (2/2014)

-----  
Found - BLM Brass Cap (properly marked) dated 1994 with the following Accessories:

22" Fir Bears N.73°E., 51.5' healed face

38" Fir Bears N.21°W., 16.5' healed face

Erroneously corrected Brooks Corner dated 1964 bears N.76°05'30" E., 28.31'

New - 14" Red Cedar Bears N.68°W. 10.8' scribed "1/4 S31 BT"  
Compass Declination: 17 1/2°E