

PRIMARY CORNER DESCRIPTION Sec cor for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2440)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 29, 30, 31 and 32 mkd. T23S S29 on NE.; R6W S32 on SE.; S31 on SW.; and S30 on NW. faces, with 1 notch on S. and 5 notches on E. edges, from which

- A Fir 18" dia., bears N.21°E., 65 lks. dist. mkd. T23S R6W S29 BT.
- A Laurel 14" dia., bears S.5°E., 50 lks. dist. mkd. T23S R6W S32 BT.
- A Laurel 18" dia., bears S.10°W., 57 lks. dist. mkd. T23S R6W S30 BT.
- A Laurel 6" dia., bears N.15°W., 30 lks. dist. mkd. T23S R6W S30 BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12702)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

T23SR6W
S30 S29
S31 S32
1957

from which

- A Fir 10" dia., bears N.64½°E., 114 lks. dist. mkd. T23S R6W S29 BT.
- A Fir 13" dia., bears S.66°E., 207 lks. dist. mkd. T23S R6W S32 BT.
- A Fir 13" dia., bears S.71°W., 72 lks. dist. mkd. T23S R6W S31 BT.
- A Fir 13" dia., bears N.27°W., 72 lks. dist. mkd. T23S R6W S30 BT.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #244, Surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13502)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the sec. cor., erroneously reestablished by Eggen, in 1957, bears West 0.15 chs. dist., set, and marked as described in the official record. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 29, 30, 31 and 32

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

I remove the iron post, and at the above corner point
 Reset the iron post 28" long, 2½" dia., 27" in the ground,
 with brass cap mkd:

T 23 S R 6 W			
S 30	S 29		
S 31	S 32		
1957			

from which new bearing trees

A Fir 10" dia., bears S.19°E., 220 lks. dist. mkd. T23S
 R6W S32 BT.

A Fir 9" dia., bears N.13°W., 103 lks. dist. mkd. T23S R6W
 S30 BT.

and the remaining bearing tree mkd. by Eggen in 1957

A Fir 13" dia., bears N.60½°E., 102 lks. dist., with a
 healed blaze.

The SE., SW., and NW. 1957 BTs have been destroyed. There
 is no suitable tree available within limits in the SW
 quadrant.

Fd. OK, DCSO, G.Langlitz, Jan. 8, 1975, C.S. File 57/17-3

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W.
 Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral
 Surveyors; and Robert H. Browning, Surveying Technician -
 under Group #'s 1266, 1637 and 1688, - surveyed June 9,
 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19499-500)

Point for the Sec. cor. at proportionate distance. There is
 no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam.,
 22 ins. in the ground, with brass cap mkd.

T23S R6W	
S30	S29
S31	S32
1994	

from which a bearing tree mkd. by Gould, Gawron, and Eggen
 A fir, 19 ins. diam., bears N. 50½° E., 108 lks. dist.,
 with healed blaze.

and a bearing tree mkd. by Brooks

A fir, 14 ins. diam., bears N. 12½° W., 122 lks. dist.,
 with healed blaze.

and new bearing trees

A fir, 10 ins. diam., bears S. 85½° E., 23 lks. dist.,
 mkd. T23S R6W S32 BT.

A fir, 11 ins. diam., bears S. 71° W., 13 lks. dist., mkd.
 T23S R6W S31 BT.

Deposit a white "DEEP-1" magnetic marker at the base and
 steel fence post alongside the stainless steel post.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec Cor for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

From this point, cor. of secs. 29, 30, 31, and 32, erroneously corrected by Brooks in 1964, bears N. 11° 04' 30" W., 0.193 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 2 ins. above the ground, with brass cap marked and witnessed as described in the official record except the SE. bearing tree marked by Brooks is a stump. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the stump.

FD. Ok by D. Edwards, May 2005 - M147-56

Ronald L. Rice, Ward NW - March 2012 - C.S. File 65/76-29

Condition report only

Found - 3¼" BLM brass cap dated 1994 with the following accessories:

22" D.Fir bears N.50½°E., 71.3' - healed face

17" D.Fir bears N.12½°W., 80.5' - healed face

13" D.Fir bears S.85½°E., 15.2' - healed face

19" D.Fir bears S.71°W., 8.6' - healed face

Inverted BLM monument bears N.11°04'30"W., 12.74' - flush to ground

Note - Corner has steel post adjacent to it.

All BT's have red painted bands and yellow tags.

Compass Declination 17° East

Fd as per 2012 report except SE BT is a stump, by R. Rice, 12/2015 - M170-39

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 10/22/2020 - C.S. File 67/46-46

Found ok

Lat: 43.533748558

Long: -123.442501357