

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2443)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S on W. face, from which
A Fir 30" dia., bears N.60°E., 67 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears N.70°W., 70 lks. dist. mkd. ¼ S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12704)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:
T23SR6W
¼
S30|S29
1957

from which
A Fir 10" dia., bears N.48½°E., 64 lks. mkd. ¼ S29 BT.
A Fir 8" dia., bears S.74½°W., 20 lks. mkd. ¼ S30 BT.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #244, Surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13505)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
From this point, the ¼ sec. cor. of secs. 29 and 30, erroneously reestablished by Eggen in 1957, bears West, 0.08 chs. dist., set, marked, and witnessed as described in the official record. I remove the iron post and at the corner point.
Reset the iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd: T 23 S R 6 W
¼
S 30|S 29
1957

from which the bearing trees mkd. by Eggen in 1957
A Fir 12" dia., bears N.44°E., 59½ lks. dist., with a healed blaze.
A Fir 7" dia., bears S.80°W., 27½ lks. dist. with a healed blaze.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19501-02)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T23S R6W

¼
S30 | S29
1994

from which a bearing tree mkd. by Gould, Gawron, and Eggen
A hemlock, 14 ins. diam., bears N. 56° W., 51 lks. dist., with healed blaze. (Record, fir.)
and a new bearing tree

A cedar, 6 ins. diam., bears N. 21½° E., 26 lks. dist., mkd. ¼ S29 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the ¼ sec. cor. of secs. 29 and 30, erroneously corrected by Brooks in 1964, bears N. 25° 34' 30" W., 0.364 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 2 ins. above the ground, with brass cap marked and witnessed as described in the official record except the bearing trees are hemlock (record, fir.) Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the NE. bearing tree.

FD. Ok by D. Edwards, May 2005 - M147-56

Ronald L Rice - For: Roseburg Resources - Dec. 2015 - M170-39

Found - BLM brass cap 1994
18" Hemlock bears N.56°W., 33.7', open face.
9" R.Cedar bears N.21½°E., 17.2, open face.
2½" inverted iron pipe monument bears N.25°34'30"W., 24.02', set below ground.
New - 12" D.Fir bears due East 21.2', blazed, scribed ¼ S29 BT
Steel post adjacent to corner.