

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2441)

Set Cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on N. face, from which
A Fir 6" dia., bears N.10°W., 33 lks. dist. mkd. ¼ S BT
A Maple 4" dia., bears S.31°E., 19 lks. dist. mkd. ¼ S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12703)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2" dia., 26" in the ground, with brass cap mkd:

T23SR6W
¼ $\frac{S\ 29}{S\ 32}$
1957

from which

A Fir 18" dia., bears S.89°E., 83 lks. dist. mkd. ¼ S32 BT
A Madrone 13" dia., bears N.79°30'W., 44 lks. dist. mkd. ¼ S29 BT.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #244, Surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13503)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the ¼ sec. cor., erroneously reestablished by Eggen in 1957, bears West, 0.08 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, and at the above corner point

Reset the iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd:

T 23 S R 6 W
¼ $\frac{S\ 29}{S\ 32}$
1957

from which

A Fir 14" dia., bears S.83°E., 87 lks. dist., mkd. ¼ S32 BT.
A Madrone snag 17" dia., bears N.67½°E., 65 lks. dist. mkd. ¼ S29 BT.

and the remaining bearing tree marked by Eggen in 1957

A down Fir 18" dia., bears S.88°E., 76 lks. dist. with a healed blaze. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

There are no suitable live trees available within limits to the North of line.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19500)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T23S R6W
S 29

¼
S 32
1994

from which

A fir, 9 ins. diam., bears N. 4 ¾° E., 35 lks. dist., mkd. ¼ S29 BT.

A fir, 9 ins. diam., bears S. 61½° E., 11 lks. dist., mkd. ¼ S32 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

The corner is located on SW. slope.

From this point, the ¼ sec. cor. of secs. 29 and 32, erroneously corrected by Brooks in 1964, bears N. 1° 57' 00" E., 1.059 chs. dist.; monumented with an iron post, 2 ins. diam., firmly set, projecting 2 ins. above the ground, with brass cap marked and witnessed as described in the official record except the remaining tree marked by Gould, Gawron, and Eggen is dead and down, the NE. bearing tree marked by Brooks is gone, and the SE. bearing tree marked by Brooks is a snag. Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on all bearing trees.