

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 3 & 4 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1428)</p> <p>-----</p> <p>Set standard cor. to secs. 3 and 4, from which A Yew 12" dia., bears S.23°W., 23 lks. dist. A Yew 8" dia., bears S.23°E., 35 lks. dist.</p>
<p>GLO survey by Carl S. Nicklin, Deputy Surveyor, under Special Instructions dated Oct. 27, 1897 (DCSO records Vol. 4 Page(s) 1472)</p> <p>-----</p> <p>I make diligent search for the standard cor. of secs. 3 and 4, but can find no sign thereof. Set a sandstone 12x10x6 ins., 8" in the ground, mkd. S C on S.; with 3 grooves on E. and W. faces, from which A Fir 20" dia., bears S.12°E., 29 lks. dist. mkd. T23S R6W S3 BT. A Fir 40" dia., bears S.49°W., 18 lks. dist. mkd. T23S R6W S4 BT. This cor. is on the SE slope of spur, 25 ft. below top.</p>
<p>BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12628)</p> <p>-----</p> <p>The standard cor., monumented by a sandstone, 12x10x6 ins., firmly set, with 3 grooves on the East and 3 grooves on the West, and SC on the S. face, from which A Fir 32" dia., bears S.20°E., 20 lks. dist., mkd. T23S R6W S3 SC BT. A Fir 48" dia., bears S.45°W., 18 lks. dist., mkd. with a healed blaze. At the corner point Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:</p> <p style="text-align: center;">T22SR6W <u>S 34</u> S 4 S 3 T23SR6W S C 1943</p> <p>Deposit stone alongside the iron post, properly oriented.</p>
<p>Fd. BC, June 1992, J. Branch, M 115-23 and M 115-26 Fd. OK, Dec. 1995, K. Hoffine, C.S. 65/2-1</p>
<p>continued next page</p>

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 3 & 4 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM rehabilitation of certain corners, Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech., under Group #2000, Surveyed April 2002, - (DCSO records Vol. 54 Page(s) 21108-9)

The standard corner of secs. 3 & 4 only, on the N. bdy. of the Tp., monumented with an iron post, 2" dia., firmly set, projecting 8" above the ground, with the sandstone set by Nicklin, 12x10x6", alongside, with brass cap (properly) mkd., from which the remains of a bearing tree mkd. by Nicklin

A fir snag, 54" dia., bears S.45°W., 11.9 ft., with a healed blaze.

and new bearing trees

A cedar, 11" dia., bears S.46½° E., 15.3 ft., mkd. T23S R6W S3 BT.

A hemlock, 22" dia., bears S.59¼°W., 31.5 ft., mkd. T23S R6W S4 BT.

The geographic position (NAD 1983) of this cor. as determined by a differentially corrected, mapping grade GPS receiver (Trimble Pro XR), observation, is as follows:
Latitude: 43°36'22.41"N., Longitude: 123°24'21.07" W.