

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2423)

Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Hemlock 12" dia., bears N.35°E., 32 lks. dist. mkd. 1/4 S BT.
A Hemlock 12" dia., bears S.50°W., 50 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12685)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:
T23SR6W
1/4 S 15
S 22
1957

from which
A Hemlock 14" dia., bears N.44°E., 25 lks. dist. mkd. 1/4 S15 BT.
A Cedar 6" dia., bears S.13°W., 59 lks. dist. mkd. 1/4 S15 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19489-90)

Point for the 1/4 sec. cor. at proportionate distance. There is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.
T23S R6W
S15
1/4 -----
S22
1994

from which a bearing tree mkd. by Gould, Gawron, and Eggen
A cedar, 16 ins. diam., bears S. 12° W., 38 lks. dist. I
remark 1/4 S22 BT. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

and a new bearing tree
A fir, 6 ins. diam., bears N. 39½° W., 96 lks. dist., mkd. ¼ S15 BT.
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
The corner is located on steep N. slope at S. edge of logged area.

From this point, the ¼ sec. cor. of secs. 15 and 22, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears N. 13° 58' 00" E., 0.207 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap marked and witnessed as described in the official record, except the NE. bearing tree is a rotted stump, bears N. 48° E. (record, N. 44° E.). Amended the marks on the brass cap to read AM 1994 1957, reset the monument inverted, and obliterated the marks on the stump.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22847)

The ¼ sec. cor. of secs. 15 and 22, monumented with an iron post, 2½" dia., firmly set, projecting 1" above a collar of stone, with a brass cap (properly) mkd. from which a bearing tree mkd. by Gould, Gawron, and Eggen
A cedar, 19" dia., bears S.12°W., 25.1 ft., with a healed blaze.
and a bearing tree mkd. by Rogers, et al, in 1986-95
A fir, 12" dia., bears N.39½°W., 63.4 ft., with a healed blaze.
Corner is located on a steep SE. bank, 30 ft. E. of a creek, 3 ft. wide, course N.50°E.
From this cor., a point erroneously reestablished by Gould, Gawron, and Eggen, bears N.17°40'06"E., 13.15 ft., monumented with an iron pipe, 2½" dia., firmly set, top 6" below ground surface.