

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2408)

Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Hemlock 10" dia., bears N.30°E., 21 lks. mkd. ¼ S BT.
A Fir 10" dia., bears S.32°W., 28 lks. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12671)

Point for the ¼ sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

T23SR6W

¼

S34|S35

1957

from which

A Fir 8" dia., bears S.13°E., 47 lks. mkd. ¼ S35 BT

A Fir 10" dia., bears S.72½°W., 121 lks. mkd. ¼ S34 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey and crew - Jan. 29, 1962 - C.S. File 52/102-21

Found - Govt. pipe, 2" with brass cap, out of ground, position for corner falls in fire trail.

8" Fir snag S.13°E., 31.0 ft. BT tag on snag. Snag faced off but never scribed.

10" Fir snag S.72½°W., 79.9 ft. BT tag on snag. Snag faced off but never scribed.

Reset brass cap in original position. Pile mound of rocks around it.

New BTs -51" D.Fir S.40°E., 74.0 ft. mkd. ¼ S35 CS BT.

8" W.Fir N.15°W., 96.0 ft. mkd. ¼ S34 CS BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy, Mike Stone, crew - Nov. 1962 - C.S. File 52/102-22

Found - Govt. brass cap set in 1957 out of ground and lying against Fir stump alongside of corner.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

51" D.Fir S.40°E., 74.0 ft. mkd. by County in 1962. Scribing still visible, tree alive and standing.
8" W.Fir N.15°W., 96.0 ft. mkd. by the County in 1962. Scribing still visible, tree still standing but badly burned and nearly dead.
10" Fir snag S.72½°W., 79.9 ft. showing blaze and BT tag.
The Fir snag mkd. in 1957 to the SE is now gone.
RESET BRASS CAP in original position.
New BT - 10" Red Cedar N.60½°W., 90.2 ft. mkd. ¼ S34 CS BT.
Corner is in East edge of fire trail.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22840)

The ¼ sec. cor. of secs. 34 and 35, perpetuated by Godfrey, in 1962, monumented with an iron post, 2" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which the remains of bearing trees mkd. by Godfrey

A roothole bears S.37¼°E., 74.0 ft., alongside of which is a down, decayed fir snag, 45" dia., with scribe marks 5 B visible on an open blaze.

A cedar, 28" dia., bears N.61°W., 88.6 ft., with fragmentary scribe marks visible on a partially healed blaze.

and a new bearing tree

A fir, 13" dia., bears N.62°E., 17.9 ft., mkd. ¼ S35 BT.