

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Section 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Resurvey - James E Jelley, Wayne L. Rogers, and Lance J. Bishop, Cadastral Surveyors Under Group # 1098 - Surveyed June 1982/Nov. 1983 (DCSO records Vol. 46 Page(s) 17741)

Point for the center 1/4 sec. cor. of sec. 26, at intersection with the E. and W. center line.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
T 23 S R 6 W
C 1/4
S 26
1982

from which
A Fir 8" dia., bears N.85°E., 12½ lks. dist., mkd. C ¼ S26 BT.
A Fir 18" dia., bears S.31½°W., 34 lks. dist., mkd. C ¼ S26 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19512)

Point for the center ¼ sec. cor. of sec. 26, at intersection with the E. and W. centerline.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
T23S R6W
C¼ S26
1994

from which bearing trees mkd. by Jelley, Rogers, and Bishop
A fir, 12 ins. diam., bears N. 43½° E., 6 lks. dist., with healed blaze.
A fir, 25 ins. diam., bears S. 47° W., 37 lks. dist., with healed blaze.
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the center ¼ sec. cor. of sec. 26, erroneously established by Jelley, Rogers, and Bishop in 1982-83, bears N. 69° 18' 00" W., 0.096 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1982 and reset the monument inverted.