

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 045020

PRIMARY CORNER DESCRIPTION NW Cor. Ziba Dimmick DLC #45

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated June 8, 1857 - DLC Volume, Page 129

Set post NW cor., from which
A Fir 15" dia., bears S.2°E., 28 lks.
A Fir 12" dia., bears N.30°W., 38 lks.

Douglas County Surveyors Office - Milo Godfrey and crew -
(C.S. 49/123-59 12/1962) & C.S. File 52/125-44 - Jan. 1966

Found 2 trees stump. One did not face right to fit had been
chopped open many years ago and burned
The other stump appears to have been laying down before it
was cut off, someone opened it up with a chain saw, but this
tree had also been opened many years before and appears
burned. No scribing visible (1st search)

Corner searched for, not found. (2nd search)

BLM survey by Harvey E. Wofford, Cadastral Surveyor, under
Group #987, surveyed July/Nov. 1979 - (DCS0 records Vol. 42
Page(s) 16591)

The NW. Cor. of DLC #45, monumented with an iron pipe, ½"
dia., firmly set, projecting 24" above ground, at the cor. of
wire fences extending E. and S. This position has long been
recognized by adjacent landowners as the cor. and is accepted
as the best available evidence of the position of the
original corner.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground,
with brass cap mkd:

T 23 S R 7 W
S 19 | DLC
 45
 1979

from which new bearing trees

A Fir 7" dia., bears S.46½°E., 31½ lks. dist., mkd. DLC 45
BT.

A Fir 8" dia., bears S.29°W., 9 lks. dist., mkd. T23S R7W
S19 BT.

Reset the iron pipe alongside the iron post.

Fd. Ok by C. Sweeden, 4/2008 - M156-11

Fd. per M156-11 by Carl Sweeden, 7/2014 - M168-30