

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 300129

PRIMARY CORNER DESCRIPTION M.C. on East bdy Sec 32

Alias <u>870080</u>	Description <u>M.C. on left bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCS0 records Vol. 6 Page(s) 2480)</p> <p>-----</p> <p>left bank of Umpqua River, where set post cor. to fractional secs. 32 and 33, from which</p> <p>    A Fir 12" dia., bears S.21°E., 39 lks. dist.</p> <p>    A Fir 20" dia., bears N.65°W., 72 lks. dist.</p>
<p>F.C. Frear; James Wolford; A. Boyer; Gene Richardson; Edgar Madison - Jan. 27, 1926 (No record source found, see "old" corner book, Page 40)</p> <p>-----</p> <p>Reset per old BTs.</p> <p>Set stake, from which</p> <p>    R.Fir 6" dia., bears S.35°W., 16 ft.</p> <p>    R.Fir 5" dia., bears N.15°30'E., 27.6 ft.</p>
<p>Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Sept. 1960 - C.S. File 49/49-9</p> <p>-----</p> <p>Found - 6" now 14" Fir S.35°W., 16.0 ft. I open and find good scribing "M S32".</p> <p>    Frear's NE. BT not found.</p> <p>    No original BTs found.</p> <p>Meander corner is in river bed. Set <u>Wit. Cor.</u> 50 ft. South.</p> <p>Set Brass cap mkd: WC 50' N. to MC T23S R7W County Surveyors Office 1960 S32/S33</p> <p>New BTs- 6" R.Fir bears S.40°W., 55.7 ft. scribed W.C. MC S32 CS BT.</p> <p>    8" R.Fir bears S.52½°E., 176.9 ft. scribed W.C. MC S33 CS BT.</p> <p>Wit. Cor. is 31.0 ft. North of centerline of County road.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone &amp; Vernon "Ray" Tracy, crew - July 1962 - C.S. File 52/125-7</p> <p>-----</p> <p>Found - Brass cap set previously.</p> <p>    8" Fir S.52½°E., 176.9 ft. scribing still visible.</p> <p>    This tree is to be removed for road construction.</p> <p>    SW. BT is gone.</p> <p>New BTs- 9" D.Fir S.53°W., 77.6 ft. mkd. "WC MC S32 CS BT".</p> <p>    9" Myrtle S.69°E., 268.0 ft. mkd. "WC MC S33 CS BT"</p> <p>Did not move brass cap at Wit. Cor. It did not appear to be in danger of being disturbed.</p>
<p>continued next page</p>

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 300129

PRIMARY CORNER DESCRIPTION M.C. on East bdy. Sec. 32

Alias 870080 Description M.C. on left bank Umpqua River  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. OK March 1983 by Don Bentz - M 90-38 A&B  
Fd. OK Nov. 1996 by D. Bentz - 1998-0064 A&B

Douglas Co. Surveyors Office - Stephen J Flause - Mike Koch  
- Aug. 4, 2014 - C.S. File 67/41-39

-----

Found - 1960 DCSO 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe protruding 12" above ground leaning M/L south 0.5 ft from plumb (Logs dumped near mon. probably tipped BC) - All fd accessories are measured from plumb position of fd BC monument.

OBT/1926- No evidence of orig. BTs or the 1926 renewal trees for the orig. meander corner position (in flood zone all washed away)

1960 - No evidence of 1960 witness corner to the meander corner BTs. SW tree position falls in cut-bank of widened road and SE tree position falls in staging area for bridge rebuild.

1962 BTs- A 9" D.Fir now a 24" dia., D.Fir with a now barely visible fully healed double blaze; bears S.53°W., 77.6 ft. (as per rec.)  
A 9" myrtle now a 13" dia. myrtle with a fully healed double blaze; bears S.69°E., 268.0 ft. (as per rec)

New - The BC monument is returned to its plumb position and now protrudes 14" above ground.  
A 7" dia. Maple scribed "WC MC S33 CS" "BT" on a double blaze; bears N.28½°E., 9.7 ft.  
A 17" dia. D.Fir scribed "WC MC S33 CS" "BT" on a double blaze; bears S.81½°E., 16.7 ft.

Note - Monument is on flat ground off of north road shoulder in scattered young fir, maple, alder and myrtle.  
Compass decl. 15½°E.

2