

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2468)

Set ¼ sec. post, from which
A W.Oak 14" dia., bears N.60°W., 18 lks. dist.
A W.Oak 12" dia., bears S.35°E., 40 lks. dist.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #330, Surveyed Aug. 1957 (DCSO records Vol. 28 Page(s) 12096)

The ¼ sec. cor. marked by the outline of the bottom of the original post in hard clay soil, containing wood fiber, 4" sq., from which the original bearing trees, which agree with the record:

A stump hole bears N.60°W., 18 lks., containing rotted wood.

A W.Fir 32" dia., bears S.35°E., 40 lks. plainly blazed and healed; I do not open.

At the corner point
Set an iron post, 30" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 7 W
¼ S 15
S 22
1957

from which a new bearing tree:
A D.Fir 38" dia., bears N.73°W., 40 lks. mkd. ¼ S15 BT.

DCSO-GIS Corner visitation - 3/7/2006 - Typed: 1/21/2011 - C.S. File 67/33-1

Monument - 2.25" BC/IP
Comment - (needs) rehap; no BTs