

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 35 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2516)

-----  
Set a Fir post for the ¼ sec. cor., from which  
A Chinquapin 6" dia., bears N.45°E., 7 lks. dist.  
A Fir 24" dia., bears S.70°E., 66 lks. dist.

BLM resurvey by Joseph S. Gawron, Cadastral Surveyor, under Group #405, surveyed June 1958 - (DCSO records Vol. 30 Page(s) 12589-90)

-----  
1/4 Cor. is monumented with a partially decayed Fir post, 2 x 2 ins., scribe marks not legible, from which the remains of the original bearing trees:

A Chinquapin stool bears N.45°E., 7 lks. dist.  
A sawed Fir stump 36" dia., bears S.70°E., 66 lks. dist.  
mkd. BT. At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 7 W  
    ¼ S 35  
    T 24 S  
    1958

from which

A Chinquapin 8" dia., bears N.64°E., 9 lks. dist. mkd. ¼ S35 BT.

A Fir 9" dia., bears N.63½°W., 108 lks. dist. mkd. ¼ S35 BT.

Fd. OK, July 1980 by C. Guile - M 79-52

Mark Smalley - For: Roseburg Resources - Sept. 2002 - M141-7

-----  
Found - 1958 Cadastral brass cap on an iron pipe  
23" Fir N.63½°W., 71.3' healed face.

New - 36" Rotten Fir stump S.70°E., 43.5'  
13" Fir N.76°W., 23.4' scribed "¼ BT"  
12" Fir N.9°E., 16.0' scribed "¼ BT"