

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 30 & 31, only (east line)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2633)

Marked a Fir, 24" dia., for the cor. to secs. 29, 30, 31 & 32, from which

- A Fir, 10" dia., bears N.10°E., 34 lks.
- A Fir, 14" dia., bears S.10°E., 26 lks.
- A Fir, 30" dia., bears S.45°W., 19 lks.
- A Fir, 30" dia., bears N.5°W., 43 lks.

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2654)

I destroyed all marks on old corner & BTs referring to these secs. (secs. 29 & 32).

Michael S. McDowell - For: Weyerhaeuser Co. - Feb. 21, 1977 - M63-23 & C.S. File 58/139

Set - 1½" gal. I.P. with brass cap, from which
6" Fir BT scribed bears S.57°30'W., 43.2 ft
4" Fir BT bears N.35°W., 22.4 ft.

NOTE: This corner set in error, see letter dated 4/12/1978 in C.S. File 58/139

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16221-2)

From the cor. of secs. 30 & 31 only, at proportionate distance in latitude & at rec. distance in departure, from the ¼ sec. cor. of secs. 30 & 31; there is no remaining evidence of the orig. cor.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T23S R9W
S 30 | S32
S 31 |
1977

Corner falls in open logged area; there are no suitable trees available within limits.

Set a 5 ft. steel fence post alongside iron post.

continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 30 & 31, only (east line)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Henry R. Reppeto - For: Weyerhaeuser Co. - April 12, 1978 -
C.S. File 58/139

Partial content of letter dated April 12, 1978 to Douglas Co. Surveyor from Weyerhaeuser:
"We have destroyed all accessories to the corners we set (NE Cor. Sec. 31 and the NW Cor.
Sec. 32) as well the East 1/4 Cor. of Sec. 31. Enclosed is a plat for the corrected position of
the East 1/4 corner of sec. 31, based on the cadastral location of the NE corner and latest GLO
record distances & bearings". See M 63-23 for orig. Weyerhaeuser map & C.S. 58/139 for
replacement.

BLM Dependent resurvey by Edith M Forkner, Cadastral
Surveyor, under Group #2756, surveyed May 2014 - (DCSO
records Vol. 58 Page(s) 23310)

The cor. of secs. 30 and 31 only, on the W. bdy. of sec. 32,
monumented with an iron post, 2 1/2" dia., firmly set,
projecting 4" above ground, with a brass cap (properly) mkd.
from which new bearing trees

A fir, 12" dia., bears S.25 1/2°W., 30.8 ft., mkd. T23S R9W
S31 BT.

A fir, 10" dia., bears N.74 3/4°W., 18.2 ft., mkd. T23S R9W
S30 BT.

Drive an aluminum angle iron alongside the cor.

NAD 1983 (2011)

Latitude: 43°31'49.09"N Longitude: 123°47'48.79"W