

PRIMARY CORNER DESCRIPTION Cor. Secs. 5 & 6 only, South bdy

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2622)

-----  
Set a Fir post 5" dia., 4 ft. long, 20" in ground for the corner to secs. 5, 6, 7, & 8, from which

- A Hemlock, 14" dia., bears N.87°E., 58 lks.
- A Hemlock, 24" dia., bears S.65°E., 80 lks.
- A Fir, 48" dia., bears S.82°W., 138 lks.
- A Hemlock, 48" dia., bears N.72°W., 84 lks.

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2656)

-----  
At the cor. of secs. 5, 6, 7 & 8, which is a fir post 5" sq. 24" high, badly decayed, marked & witnessed as described by the surveyor general. I destroyed all marks referring to secs. 7 & 8.

Arnold G. Gibson - For: Ore. State Bd. of Forestry - Oct. 26, 1967 - C.S. File 55/68-4

-----  
Found - Original post, now missing, fd. orig. lines blazes N) from which:  
14" Hemlock bears N.87°E., 58 lks., now a rotted windfall.  
24" Hemlock bears S.65°E., 80 lks., now a rotted windfall.  
48" Fir bears S.82°W., 138 lks., now 72" with face overgrown.  
48" Hemlock bears N.72°W., 84 lks., now a 48" rotted stump, remains of orig. axe work around face.  
32" Hemlock bears S.77½°W., 33.9 ft., with scribed T23S R9W S5 BT facing SW (68 years overgrowth)  
Stream, 1 lk., course N.10°W., bears North 523 lks., now in place.  
Survey by Oscar Thiel (1899) reported destroying SE & SW BTs.  
Stream, 3 lks., course N.60°W., East 425 lks., now in place.  
North ¼ cor. 7 bears N.89°45'W., 725 lks., now in place.  
County road bears N.89°45'W., 210 lks., remains now in place.  
Set - 1½"x36" galv. iron pipe with 3" brass cap mkd: Ore. St. Bd. of Forestry T23S R9W S6 S5 1967 RS359, 34" in ground, in mound of rock, and from which:  
20" Hemlock bears N.67°E., 41.6 ft. to face scribed: T23S R9W S5 CS BT continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 5 & 6 only, South bdy

Alias	Description
Alias	Description
Alias	Description
Alias	Description

24" Hemlock bears N.54°W., 45.4 ft. to face scribed:  
T23S R9W S6 CS BT RS 359

Set - 4" x 4" x 72" white painted Cedar post 1 ft. NW of corner pipe. Oregon St. Forestry Dept. metal location poster on the 20" Hemlock BT.

Fd. & used on BLM Dependent resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group #703 surveyed July 1969 - May 1970 - (DCSO records Vol. 35 Page(s) 14566)

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23222-3)

-----

The cor. of secs. 5 & 6 only, on the N. bdy. of sec. 7; monumented with an iron post, 1½" dia., firmly set, projecting 3" above ground, in a collar of stone, with a brass cap (properly) mkd.  
from which the remains of the original bearing trees

- A fir, 81" dia., bears S.80°W., 91.1 ft., with a healed blaze.
- A very decayed hemlock stump, size indeterminate., bears N.78°W., 57.4 ft., with no marks visible.

and a bearing tree mkd. by person(s) unknown

- A hemlock, 37" dia., bears S.75°W., 34.0 ft., with no marks visible on a partially healed blaze facing away from the cor.

and the BTs mkd. by Gibson, in 1967 (Record, County Surveyor)

- A decayed hemlock stump, 24" dia., bears N.65°E., 42.6 ft., with scribe marks T23 and other illegible scribe marks visible on decayed open blaze.
- A hemlock, 35" dia., bears N.55°W., 46.9 ft., with a healed blaze.

and a new bearing tree

- A hemlock, 18" dia., bears N.2½°E., 22.6 ft., mkd. T23S R9W S5 BT.

From the corner  
S.89°33'23"E., 305 ft., creek, 1 ft. wide, course N.45°W.  
Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.  
Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.  
An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description. \_\_\_\_\_ Cont.

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Cor. Secs. 5 & 6 only, South bdy

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. Ok by R. Quimby Dec. 2018 - C.S. File 65/102-11