

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 7 Page(s) 2876-77) and duplicate Page 2764)

 Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 7, 12, 13 and 18, marked T24S S7 on NE.; R1W S18 on SE.; R2W S13 on SW.; and S12 on NW. faces, with 2 notches on N. and 4 notches on S. edges, from which
 A Fir 24" dia., bears N.75°E., 26 lks. dist. mkd. T24S R1W S7 BT.
 A Fir 30" dia., bears S.81°E., 30 lks. dist. mkd. T24S R1W S18 BT.
 A Hemlock 32" dia., bears S.75°W., 46 lks. dist. mkd. T24S R2W S13 BT.
 A Fir 20" dia., bears N.61°W., 50 lks. dist. mkd. T24S R2W S12 BT.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2941)

 Found Sec. corner which is a post 4 ft. long, 4" sq., set 24" in the ground, marked and witnessed as described by the Surveyor General. This cor. is correct in position.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Aug. 1969 - C.S. File 54/27-255

 Found - Orig. 24" now 30" Fir, dead, N.75°E., 17.2 ft., bark scribe visible, poor condition.
 Orig. 30" now 34" Fir, dead, S.81°E., 19.8 ft., fragmentary bark scribe visible.
 Orig. 32" now 36" Hemlock, alive, S.75°W., 30.4 ft., scribe visible on unhealed blaze. We rescribe "T24S R2W S13 CS BT".
 Orig. 20" now 24" Fir snag, N.61°W., 36.3 ft. (Rec. 33 ft.), bark scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office

R	T 24 S	R
2	S 12 S 7	1
W	S 13 S 18	W
1969		

New BTs- 16" Hemlock N.46°E., 30.0 ft. mkd. T24S R1W S7 CS BT
 10" Hemlock N.6°W., 22.3 ft. mkd. T24S R2W S12 CS BT
 22" Hemlock S.43°E., 59.5 ft. mkd. T24S R1W S18 CSBT
 Cor. lies on steep n'therly slope 90 ft. S of creek, course E.

(Cont. Next Page)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Corner Fd. and used in BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1533, Surveyed May 1990 - (DCSO records Vol. 50 Page(s) 18994)

Douglas Co. Surveyors Office - Stephen Flause and Terrie Franssen, crew - Nov. 8, 1990 - C.S. File 64/11-4

CONDITION REPORT ONLY

Found:

- A 2½" brass cap on an iron pipe set approx. flush with ground. (1969 cap)
- Orig. BT, a 24" Fir now 30" dia. 1½ ft. tall stump with no bark scribing visible, bears N.75°E., 17.9 ft. dist. (Rec. N.75°E. 17.2 ft., probable face measurement)
- Orig. BT, a 30" Fir now a 36" dia. 3½ ft. tall Fir stump with no bark scribing visible, bears S.81°E., 20.7 ft. (Rec. S.81°E., 19.8 ft., probable face measurement.)
- Orig. BT, a 32" Hemlock now a 38" DBH Hemlock with illegible scribing visible in a partially healed single blaze, bears S.79°W., 30.4 ft. (Rec. S.75°W., 30.4 ft.)
- Orig. BT, a 20" Fir now a 20" dia. 1½ ft. tall rotted Fir stump with no bark scribing visible, bears N.59°W., 35.3 ft. (Rec. N.61°W., 33.0 ft.)
- A 10" Hemlock now an 11" DBH 6 ft. tall metal capped Hemlock stump with the scribing 24S R2W S12 CS BT visible in a partially healed single blaze, bears N.6°W., 22.3 ft.
- A 22" Hemlock now a 22" 4½ ft. tall metal capped Hemlock stump with the scribing T24S R1W S18 CS BT visible in a partially healed single blaze, bears S.43°E., 59.5 ft.

NE. BT gone due to a road work.

No suitable line trees nearby. All found stumps are in good condition except one rotted stump as noted. Cap lies on steep northerly slope above cut bank for logging spur road.