

PRIMARY CORNER DESCRIPTION CC for Sec. 6; & Sec. 1, T24-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 - (DCSO records Vol. 7 Page(s) 2963)

-----  
(At a point 4.38 chs. West of cor. to Tps. 23 & 24 S., Rs. 2 & 3 W)  
I Set a Yew post 4½ ft. long, 4" sq., 24" in the ground for closing cor. to Tp. 24 S., Rs. 2 & 3 W. mkd. CC T24S on S.; R2W S6 on E.; and R3W S1 on W. faces with 6 notches on S., E., and W. faces, from which  
    A Hemlock 5" dia., bears S.25°E., 46 lks. dist. mkd. T24S R2W S6 BT.  
    A Hemlock 14" dia., bears S.25°W., 19 lks. dist. mkd. T24S R3W S1 BT.  
    A Hemlock 6" dia., bears N.25°E., 35 lks. dist. mkd. T23S R2W BT.

GLO survey by Henry L. Chandler, Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2936) (and Page 2938)

-----  
(Page 2936)  
The cor. to Tp. 24 S., Rs. 2 and 3 W., which was established when the range line between Tp. 24 S., Rs. 2 and 3 was run, found to be wrongly located. Therefore, I destroyed it.  
(Page 2938)  
At point of intersection (11.80 chs. West of the SE. cor. to T23S R3W) Set a post 4½ ft. long and 4" sq., 24" in the ground for closing cor. to secs. 1 and 6, T24S Rs. 2 & 3 W., marked CC T24S on S.; R2W S6 on E.; and R3W S1 on W. faces, 6 notches on S., E., and W. faces, from which  
    A Fir 60" dia., bears S.70°E., 56 lks. dist. mkd. T24S R2W S6 BT.  
    A Yew 18" dia., bears S.24°W., 59 lks. dist. mkd. T24S R3W S1 BT.  
    A Fir 60" dia., bears N.37°W., 32 lks. dist. mkd. CC T24S Rs. 2 and 3 W BT.

Weyerhaeuser Company - 1957-1963 - C.S. File 53/111-1

-----  
Found - 60" Fir S.70°E., 37.0 ft., now blown down.  
          18" Yew, now 20" Yew, S.24°W., 39.0 ft. OK.  
          62" Fir N.30°W., 8.6 ft. OK.  
Set 1/2" Galv. I.P., W. Co., 1954.  
BT - 64" Fir, East 42.8 ft. "W" nail and plates.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION CC for Sec. 6; & Sec. 1, T24-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
 April 1, 1968 - C.S. File 54/27-216

-----  
 Found - 1/2" I.Pipe at corner and "W" BTs.  
           Orig. 18" now 20" Yew, alive, S.30°W., 39.0 ft.,  
           scribe marks visible on old blaze. Rescribe  
           "T24S R3W S1 CC CS BT".  
           Orig. 60" Fir, now 62" stump, slightly out of  
           position, S.70°E., 37.0 ft., shows good scar.  
           No trace of NW. original BT.

Set Brass cap at cor. mkd: County Surveyors Office  
 (Rese I.P. alongside)           T23S   R             C  C     R  
   T24S   3W   S 1 | S 6   2W  
   1968

New BT - 14" Yew S.50°E., 54.8 ft. mkd. T24S R2W S6 CC CS BT.  
 All "W" BTs now stumps. No other trees suitable for BTs.  
 Corner lies on bench sloping SW. in logged off area.

H.E. Case; D.L. Ellis - For: Weyerhaeuser Co. - June 8, 1970  
 - C.S. File 53/111-26

-----  
 Found - No trace of 1894 post.  
           60" Fir S.70°E., 56 lks., (37.0 ft.),; Fir stump  
           uprooted, scribing visible.  
           18" now 20" yew, S.24°W., 59 lks. (39.0 ft.),  
           visible scribing.  
           60" Fir, N.37°W., 32 lks., nothing at this brg. and  
           dist. but found scribing visible on a 62" Fir  
           stump N.30°W., 8.7 ft.  
           64" Fir stump, East 42.8 ft. (1963 Wey. co. BT)  
           1968 DCSO brass cap at corner point.

No new accessories were made but references in effect as of  
 June 8, 1970: (with plates and "W" nails)  
           50" Fir stump N.30°W., 8.6 ft.           Orig. BT.  
           20" Yew S.24°W., 39.0 ft.            Orig. BT.  
           64" Fir stump, East 42.8 ft.           W.Co. 1963