

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 360220

PRIMARY CORNER DESCRIPTION SE 1/16 Cor. Sec. 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

V.W. Hosford - Dec. 1953 - C.S. File 40/110

Set - 4" Hemlock post for corner.
 A Hemlock, 10", bears N.32½°E., 27.8 ft., mkd: 1/16 S28
 PS 253 BT.
 A Cedar, 10", bears East 31.1 ft., mkd: 1/16 S28 PS
 253 BT.

V.W. Hosford - Sept. 1957 - C.S. File 42/306-8

At the SE 1/16 S28, the BTs marked in my survey of 1953 are
in good condition. At the true point of the corner I drove a
1½" iron pipe 30" long 18" in the ground.
(See C.S. 42/306-8 for E1/16 secs 28/33 & S1/16 secs 28|27

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 12/17/2025 - C.S. File 67/61-54

Found - 1½" iron pipe leaning approx. 1' south. Returned to
 plumb position, up 4".
 Metal post 1 ft. South.
New - Sawn - burnt 19" x 1 ft. fir stump S.40°E. 4.4 ft.
 3½" mag nail, top center.
 Burnt - sawn 12" x 1½ ft. fir stump. S.64°W. 8.5 ft.
 3½" mag nail, right side center.
Notes - Mon. in very recent clearcut.
 Area burnt 9/2020
 Mon. on gentle South slope approx. 40 ft. South of
 a gravel rd.
Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43.45191053 N.
122.93626834 W.