

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2957)

Set post cor. to secs. 29, 30, 31, & 32 from which
A fir, 48" dia., bears N.70°E., 48 lks.
A W.Fir, 16" dia., bears S.20°E., 32 lks.
A fir, 8" dia., bears S.45°W., 20 lks.
A fir, 12" dia., bears N.62°W., 30 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy -
Witnesses: G. Welker & J. Fee - For: Roseburg Lumber Co. -
Oct. 29, 1956 - C.S. File 47/132

Found - 1½" iron pipe at corner & SW orig. BT bears S.60°W.,
rec. S.45°W.
Stump of orig.. NE BT cut low, no scribing, check
bearing & dist.
Rotted base of orig. SE BT, check dist. & bearing
S.4°E., rec. S.20°E., no scribing.
Up rooted SW BT now 18" S.52°W., 18.0 ft. I do not
open.

Set brass cap alongside 1½" iron pipe mkd. Sec. Cor. 30|29
County Surveyors Office 1956 T24S R3W 31|32
12" Cedar bears S.6°W., 13.3 ft. scribed T24S R3W
S31 CS BT.
10" Cedar bears S.84°W. 35.3 ft. scribed T24S R3W
S30 CS BT.
8" R.Fir bears N.40°E., 41.5 ft. scribed T24S R3W
S29 CS BT.
10" Hemlock bears S.79°E., 29.3 ft. scribed T24S R3W
S32 CS BT.

BLM dependent resurvey by Wm. W. Glenn, Cadastral Surveyor,
under Group #416, surveyed Sept/Oct 1958 - (DCSO records Vol.
30 Page(s) 12596-7)

The cor. of secs. 29, 30, 31, & 32, monumented & recorded by
Byron in 1956, at rec. dist. from the orig. BTs with an iron
post, 1" dia., firmly set 12" above ground, with brass cap
mkd. T24S R3W SEC COR 29 30 31 32 1956

from which orig. BTs:
A sawed fir stump, 65" dia., bears N.66½°E., 48 lks., with
no scribe marks visible. (Rec. bearing N.70°E.)
A rotted hemlock turnout, 13" dia., bears S.45°W., 20
lks., with no scribe marks visible. (Rec. BT a fir)
A hemlock turnout, 26" dia., bears N.62°W., 30 lks., with
no scribe marks visible. (Rec. BT, a fir)
continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

and BTs by Byron, County Surveyor, in 1956;
 A fir, 10" dia., bears N.34½°E., 63 lks., with scribe marks 24S R3W S29 BT visible on partially healed blaze.
 A hemlock, 10" dia., bears S.82½°E., 45 lks., with scribe marks S32 CS BT visible on partially healed blaze.
 A cedar, 12" dia., bears South, 20½ lks., with scribe mks T24S R3W CS BT visible on open blaze.
 A cedar, 9" dia., bears S.78½°W., 54 lks., wit scribe marks T24S R3W S31 CS BT visible on partially healed blaze.

At the corner point
 Set an iron post, 28" long, 2½" dia., 26" in the ground, with brass cap marked:

T24S	R3W
S 30	S 29
S 31	S 32

and new BT
 A hemlock, 6" dia., bears N.72½°W., 49½ lks., mkd: ¼ S30 BT.
 Reset county surveyors post alongside the iron post.

Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121 - 58 A&B

Found - Douglas county brass cap dated 1956
 24" cedar, S.3°W. 13.2', rec. S.6°W. 13.3', 1956 Do. Co.
 16" cedar, S.84°W. 35.8', rec. S.84°W. 35.3', 1956 Do. Co.
 18" hemlock, S.84°E. 29.3', rec. S.79°E. 29.3', Do. Co.
 18" fir snag, N.28°E. 31.3' - rec. unknown
 Hemlock snag, N.75°W. 32.4' - rec. unknown
 New BTs- 8" Hemlock, N.7°W. 22.3' - scribed "T24S R3W S30 BT"
 6' Fencepost 1' north.

Fd. Ok by R. Ward, 12/2001 - M 139-34

Douglas Co. Surveyor's Office - Crew: Stephen Flause & Mike Koch - 4/22/2016 - C.S. File 67/44-9

Found - A 1" (I.D.) Iron pipe by Byron, in 1956 per C.S. 47/132, firmly set, projecting 11" above the ground with a 2½" dia. brass cap (properly) mkd.
 A light metal fencepost projecting 5 1/2' above the ground bears south, 1 ft. (M 121-58 rec. North, 1 ft.)
 No evidence on the 1958 USBLM monument was found.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BTs by Byron in 1956 per C.S. 47/132 -
A 26" dia. x 6' tall broken and rotted stob bears N.34½°E., 41.5 ft. (1958 USBLM rec. 63 lks.)
A 24" dia. x 18" tall broken & rotted hemlock stump bears S.82½°E., 29.3 ft. with no blaze or scribe evidence remaining. (1958 USBLM rec. 45 lks.)
A 31" dia. R.Cedar bears south 13.3 ft. with no visible blaze. (1958 USBLM rec. 20.5 lks.)
A 23" R.Cedar bears S.78½°W., 35.3 ft. with no visible blaze. (1958 USBLM rec. 54 lks.)
A BT by Wm. Glenn, USBLM Cadastral surveyor in 1958 -
A 13" dia. x 18' tall hemlock snag bears N.76½°W., 32.7 ft. (1958 USBLM rec. N.72½°W.)
BTs by D. Baker in 1994 per M121-58 -
A 23" dia. Fir stump rotted to ground bears N.26½°E., 31.3 ft. (Rec. N.28°E., 31.3 ft.)
A 10" dia. x 12" high rotted hemlock stump bears N.7°W., 22.3 ft. with no blaze evidence remaining.
New BTs- A 25" dia. R.Cedar bears N.30½°E., 59.9 ft. scribed "T24S R3W S29 CS BT".
A 23" dia. Maple bears N.47½°W., 33.7 ft. scribed "T245 R3W S30 CS BT".
Location & comments - All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to a nail in the side and center of the root crown unless otherwise noted.
The corner falls on a moderate east slope approximately 150 west of an abandoned dirt logging road in a scattered very old reprod. forest remaining between a old clearcut in the NW Quadrant & a newer clearcut unit in the SE quadrant.
Compass declination: 15°E.