

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records Vol. 7 Page(s) 3043)  
-----  
Set ¼ sec. post from which  
    A W.Oak, 10" dia., bears N.21°E., 46 lks.  
    A B.Oak, 10" dia., bears N.14°W., 44 lks.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co.  
Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File  
53/9-86(B)  
-----  
Reported as not found.  
Found - 1½" iron pipe extending 24" above ground in fence  
cor. (fences approx. North, South & East) No BTs found no  
rec. of renewal.

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor,  
under Group #979, surveyed May/Sept. 1979 (DCSO records Vol.  
42 Page(s) 16396)  
-----  
The ¼ cor. determined at the intersection of old fence lines,  
extending N., S., & E., perpetuated by person(s) unknown,  
monumented with an iron pipe, 1½" dia., firmly set,  
projecting 14" above ground. This position is harmoniously  
related to existing orig. corners, and is accepted as the  
best available evidence of position of the orig. corner.  
At the corner point  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with  
brass cap mkd:           T24S R4W  
                                  ¼  
                                  S29 | S28  
                                  1979  
from which  
    A Fir, 10" dia., bears S.43½°E., 34½ lks., mkd: ¼ S28 BT.  
    A Fir, 6" dia., bears N.29¼°W., 37 lks., mkd: ¼ S29 BT.  
Reset iron pipe alongside iron post.

Fd. OK by M. Heimbürger - 11/1992 M 116-18  
Fd. OK by H. Christensen 1/1996 M 123-36