

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM resurvey by George M. Winter, Cadastral Surveyor under Group No. 2656, surveyed Sept./Nov. 2012 - (DCSO records Vol. 58 Page(s) 23006)

The ¼ sec. cor. of secs. 14 and 15, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground, with brass cap incorrectly (properly) mkd. from which the remains of an original bearing tree
 A decayed fir stump, bears S.78°E., 22.4 ft., alongside of which is a fallen, decayed fir snag, 24" dia., with no marks visible.
and the remains of a BT mkd. by Godfrey, in 1963
 A sawed fir stump, 18" dia., bears N.32½°E., 54.1 ft., with a healed double blaze.
and the remains of a bearing tree mkd. by Jelley in 1979
 A sawed fir stump, 18" dia., bears N.21¼°W., 28.0 ft., with a healed blaze.
and new bearing trees
 A fir, 16" dia., bears N.5°E., 71.1 ft., mkd. ¼ S14 BT.
 A fir, 17" dia., bears N.77½°W., 54.3 ft., mkd. ¼ S15 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.