

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34; & 3 & 4 of T25-5

Alias <u>047010</u>	Description <u>WSW Cor DIC #40</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Robert Elder, Contract #31 dated April, 1853 (DCSO records Vol. 7 Page(s) 3087)</p> <p>-----</p> <p>Set post cor. to Secs. 3, 4, 33 and 34, from which A W.Oak 30" dia. bears N.9°W., 310 lks. A W.Oak 24" dia. bears N.30°E., 310 lks.</p>
<p>Survey for Janssen, Evirt &amp; Morris, 1912 - F.B. 30 Pg. 31</p> <p>-----</p> <p>Set stake mkd. Cl 40 C.S.B.T. - Also mkd. A Fir 12' dia. bears N.86¼°E., 144 lks.</p>
<p>F.C. Frear, Roadmaster - April 1933, Co. Rd. 22 Plan 2 of 2</p> <p>-----</p> <p>Fir 12" N.86¼°E., 144 lks. This tree cut off &amp; rotten, mark visible. Corner reset by Frear from Wit. tree above. Set a 1" x 4 ft. G.I.P. Marked a 16" Fir N.72½°E., 33.8 ft.</p>
<p>Fred L. Dow, For: Ray Davis - March 1954 - C.S. File 50/30</p> <p>-----</p> <p>Found 1" Iron pipe. Rotten stump original BT, 24" Oak N.30°E., 310 lks.</p>
<p>James W. Byron, Deputy - Milo Godfrey; Clete Putnam March 17, 1960 - C.S. File 49/124-34</p> <p>-----</p> <p>Found - ¾" Iron pipe at corner. Now 28" Fir N.72½°E., 33.8 ft. shows good scars. No brass cap set. New BTs - 10" Laurel bears N.28°W., 124.0 ft. scribed T24S R5W S33 CS BT. 18" Fir bears S.22½°E., 58.0 ft. scribed T25S R5W S 3 CS BT. 4-Way fence corner is 12 ft. North.</p>
<p>Found 11/87, M. Heimbürger - M 101-30</p>
<p>Douglas Co. Surveyors Office - Randall Smith; Stephen Flaue January 10, 1989 - C.S. File 62/61-4</p> <p>-----</p> <p>Found - A ¾" I.D. Iron pipe 45" long, out of ground leaning against fence. A hole 1½ ft. long by 6" wide &amp; 6" deep was found at probable corner position. 16" now 36" dia. D.Fir with a fully healed single blaze bears N.70½°E., 33.8 ft. (Rec. N.72½°E., 33.8 ft.)</p> <p>continued next page</p>

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34; & 3 & 4 of T25-5

Alias 047010 Description WSW Cor. DLC #40  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

10" now 25" dia. Madrone with a fully healed double blaze bears N.28°W., 124.0 ft. (agrees w/rec.)  
18" now 26" dia. D.Fir with a fully healed double blaze bears S.24°E., 57.2 ft. (Rec. S.22½°E., 58.0 ft. dist. is a possible slope measurement)  
No other BTs found.  
Set - A 2¼" dia. brass cap on a 30½" long, 1 3/8" O.D. I.P. is set at North end of previously described hole as the most probable position of section corner. Brass cap/Iron pipe protrudes 7" above ground. ¾" I.P. is set along south edge of BC/IP & protrudes 5" above ground  
No new accessories.  
Corner is approx 13 ft. south of a four way fence corner in south running fence line. Sec. Cor. is also the SW DLC Cor. of Claim 40 in T.24-5.

Found OK, Donald Bentz, Nov. 1992, M 116-42  
Found Ok, Romanso Ware, Jun 1993, 1993-0042 & 1993-0043  
Found OK, Donald Bentz, Feb 1995, 1995-0031  
Found OK, David Collier, Nov. 1996, 1997-0006  
Fd. OK by C. Sweeden, Jan 2000 - M134-12  
Fd. Ok by C. Sweeden, Feb. 2002 - M 139-53  
Fd. OK by Ryan Erickson, 1/2015 - 2015-0003A