

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 606700

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 35 & 36 only, T23-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2516)

Set a Hemlock post for the cor. to secs. 35 and 36, from which

A Fir 16" dia., bears N.42°W., 63 lks. dist.

A W.Fir 14" dia., bears N.51°E., 71 lks. dist.

Claude Kerr - March 1949 - C.S. File 40/190

Found - 16" Fir snag with scribe visible

31" W.Fir with old BT scars.

Set a 4" x 4' Cedar stake for corner.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Ray Irving, chainman - May 25, 1955 - C.S. File 46/24

Found - Rotted stump of O.B.T. recorded 16" Fir, N.42°W., 40.9 ft. Stump now only 12". The upper part of stump rotted. No scribing visible. We cut out old blaze at base and find old blaze and scribing "B" "T".

I also find W.Fir stump that shows old blaze. We do not cut out.

Both stumps check for bearing and distances. The W.Fir stump is now 36".

Set a 1" Iron pipe with brass cap at corner marked

$$\begin{array}{r} 35|36 \text{ T } 23 \text{ S} \\ \hline 2|1 \text{ T } 24 \text{ S} \end{array} \text{ R7W}$$

County Surveyors Office 1954

Bark scribe:

A 40" R.Fir, N.80°W., 22.0 ft. S35 T23S R7W CS BT.

Blaze and scribe:

~~14" W.Fir S.80½°E., 109.0 ft. mkd. S1 CS BT.~~

~~14" W.Fir S.57°W., 57.2 ft. mkd. S2 CS BT.~~

No trees near in NE. quad.

(Corrections OK, F. Darby - Jan. 27, 1958)

BLM resurvey by Orville Eggen, Cadastral Surveyors, under Group #244, surveyed May/Aug 1957 (DCSO records Vol. 30 Page(s) 12620-21)

The Sec. cor., perpetuated and recorded by the County in 1955, at record bearing and distance from the only remaining original bearing tree, monumented with an iron pipe, 2" dia., protruding 8" above ground, firmly set, with brass cap mkd.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 35 & 36 only, T23-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

in 1955, from which the original bearing tree:
The easterly of a sawed double Fir stump, 20" dia., bears N.51°E., 71 lks. dist., with scribe marks BT visible on a partially opened blaze.

and a County Surveyors bearing tree:

A Fir 40" dia., bears N.80°W., 33 lks. dist. mkd. T23S R7W S35 CS BT.

At the corner point

Set an iron post, 28" long, 2 ½" dia., 18" in the ground, with brass cap mkd:

T 23 S R 7 W
S 35 | S 36
1957

from which

A Cedar 9" dia., bears N.34°E., 205 lks. dist. mkd. T23S R7W S36 BT.

A Fir 8" dia., bears N.25°W., 39 lks. dist. mkd. T23S R7W S35 BT.

Deposit County Iron pipe alongside the iron post.

Fd. OK, July 1980 by C. Guile - M 79-52

BLM resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1637, surveyed May 1992/April 1993 - (DCSO records Vol. 51 Page(s) 19544)

The cor. of secs. 35 and 36 only, monumented with an iron post 2½" dia., firmly set, projecting 10" above the ground with brass cap mkd. in 1957, from which the remains of a bearing tree mkd. by Byron in 1955:

A Fir stump 36" dia., bears N.80°W., 33 lks. dist., no marks visible.

and a bearing tree mkd. by Eggen:

A Cedar 24" dia., bears N.34°E., 205 lks. dist., with healed blaze.

and a new bearing tree:

A Fir 13" dia., bears N.80°W., 47 lks. dist. mkd. T23S R7W S35 BT.

The corner is at the end of a wire fence line extending E.

Fd. OK, Jan. 1994 by C. Mulkins - M 118-61

Douglas Co. Surveyors Office - Stephen J. Flaue - Mike Koch - July 18, 2014 - C.S. File 67/41-30

From the 1957 BLM resurvey

Found - A 3¼" dia., brass cap (properly mkd) on a 2" I.D. iron pipe is set plumb protruding 10" above ground.

continued next page

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From the 1955 DCSO renewal
Found - 2½" dia., brass cap (corrected by DCSO in 1958 (to be properly mkd)) is set plumb on the westerly edge of the (BLM) brass cap and protrudes 9" above ground.

Accessories are measured from the BLM brass cap

OBT - The NW tree falls under existing grave road edge. Rotted fir wood is in ground near record bearing and distance of orig. NE BT.

1955 BT (retained after 1958 correction) -

A 40" R. Fir now a 48" dia., 2 ft. tall broken and rotted fir stump with no blaze evidence bears N.80°W., 22.0 ft. (as per rec)

No evidence remains of the two erroneously marked 14" firs.

1957 BTs- A cedar 9" dia., now a 38" dia., I. Cedar with a barely visible healed blaze; bears N.34°E., 135.3 ft. (as per rec.)

A fir 8" dia., is now an almost completely rotted and scattered fir stump near record B & D.

1992-93 BLM -

A fir 13" dia., now a 22" dia., G. Fir with a fully healed double blaze; bears N.80°W., 30.1 ft. (Rec. N.80°W., 31.0 ft. possibly to trunk not C.R.C.)

New - A 5" dia. D. Fir scribed "X" "CSBT" on a double blaze; bears N.41½°E., 27.0 ft.

An 8" dia., G. Fir scribed "T23S R7W S35 CS" "BT" on a double blaze; bears N.61¾°W., 14.7 ft.

Also a 2½"x2½" steel fence post firmly set and protruding 3.5 ft. above ground; bears N.12°E., 3.5 ft. (This post is an end anchor for an unmaintained wire fence running east.)

Note - Monument is in older fir reprod forest on M/L flat ground which quickly rises to east. An intersection of two graveled roads bears N.73°W., 75 ft.

Compass decl. 15½°E.