

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 240400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3647)</p> <p>-----</p> <p>Set basalt stone 16x10x7", 11" in the ground for ¼ sec. cor. marked ¼ on N face, from which</p> <p> A maple, 14" dia., bears N.69°W., 14 lks., mkd: ¼ S17 BT.</p> <p> A fir, 21" dia., bears S.68°W., 11 lks., mkd: ¼ S20 BT.</p>
<p>Glen McChesney, WEYCO - 2/27/1957 - C.S. File 53/112-25</p> <p>-----</p> <p>Found - Stone not found, steep hillside, slide. Orig. BTs fd ok</p> <p>Set - Post, set by called dist. & bearing from GLO orig. notes. 44" Fir N.84°E., 28.5 ft. "W" nail & plate. 28" Fir (OBT) S.72°W., 7.0 ft. added "W" nail & plate.</p>
<p>V. W. Hosford - June 7, 1957 - C.S. File 42/302</p> <p>-----</p> <p>Found - 14" Maple N.69°W., 14 lks., destroyed in logging. 17" I.Cedar S.40°E., 47.9 ft., new resurvey good. 21" now 30" Fir S.68°W., 11 lks., covered orig. good USBLM</p> <p> Corner identified by SW BT & transit point on previous survey.</p> <p>Set - Orig. stone gone, I set 1½" iron pipe 36" long, 24" in ground. As no trees remain standing near in Sec. 17, I marked new BT in sec. 20 & drove iron pipe at point of ¼ corner.</p>
<p>BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13239-40)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 17 & 20, perpetuated & recorded by Hosford, in 1957, monumented with an iron pipe, 36" long, 1½" dia., firmly set 30" in the ground, from which original BTs</p> <p> A fir, 32" dia. bears S.68°W., 11 lks. with a healed blaze</p> <p> A down maple, 16" dia., bears S.51°W., 29 lks., with a healed blaze. (Rec bearing distance, N.69°W., 14 lks.)</p> <p> This tree has slid out of position with no remaining evidence of the stump hole.</p> <p>and a tree marked by Hosford in 1957</p> <p> A cedar, 20" dia., bears S.41°E., 74 lks., with scribe marks T25S R2W ¼ S20 RS253 BT visible on unhealed blaze</p> <p>At the corner point continued next page</p>

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 240400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set an iron post, 28" long, 2½" dia., 24" in the ground & in a mound of stone, 2 ft. base, to top, with brass cap marked

¼ $\frac{S\ 17}{S\ 20}$
T25S R2W
1962

No suitable bearing tree available in Sec. 17.
Deposit iron pipe alongside the iron post.

Fd. Ok by G. Baughman, 1/1976 - M56-35

Mark Smalley, Roseburg Forest Products - Bill Olsen - Niel Danko - Aug. 5, 2008 - C.S. File 65/63-32

Found - 1962 2½" iron post & brass cap (properly marked)
20" cedar S.41°E., 74 lks., rotten stump.
32" Fir S.68°W., 11 lks., tall rotten stump healed blaze.

New - 14" Fir S.62°E., 34.2 ft. scribed ¼ S BT.
7" Fir N.70°W., 14.4 ft. scribed ¼ S BT.
16" W.Fir N.18°E., 17.6 ft. scribed ¼ S BT.
12" Fir N.58°E., 12.0 ft. scribed ¼ S BT.
Compass decl. 16°E.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 12/17/2024 - C.S. File 67/59-30

Found - ¾" BLM brass cap (properly mkd) with 1¼" I.D. iron pipe on South edge.
10"x2 ft. burned, rotted Fir stub, S.68°W., 7.3 ft. (rec. 11 lks)
5"x1½ ft. burned rotted broken Fir stub N.70°W., 14.4 ft.

Un-recorded BTs
19"x2½ ft. sawn-burned Hemlock stump S.16°W., 17.8 ft., alum nail left side center, burnt face BT still legible.
17"x2 ft. Fir stump S.60°W., 12.0 ft., healed blaze, alum nail left side center.

Note - Mon is on steep south slope, approx 50' north of narrow bench in large clearcut.
Mon is approx 200' south of gravel road.
Area burnt 9/2020
Compass decl. 14½°E.

OCRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N 202319.589 E 262583.661