

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T24-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BRASS CAP TO BE RESET AFTER ROAD CONSTRUCTION.

Accessories added this date:

48" Fir S.49°E., 71.2 ft. with W nail and plate.

40" Fir S.71°W., 69.0 ft. with W nail and plate.

38" Fir N.36°W., 72.9 ft. with W nail and plate.

Frank Williams (work done by Glen McChesney) - For:
Weyerhaeuser Co. - 2/20/1981- C.S. File 58/8-30

Found - 42" Hemlock N.11¼°W., 27.4 ft. - gone.
14" Red Cedar S.35°W., 52.6 ft. - gone
48" Fir stump, S.49°E., 71.2 ft. w/W nail, plate OK
40" Fir stump, S.71°W., 69.0 ft. w/W nail, plate OK
38" Fir stump, N.36°W., 72.9 ft. w/W nail, plate
(stump was burned, W nail intact but plate was
gone so renewed plate w/same bearing & dist.

BT added Aug. 1978:

54" Fir stump, N.31°W., 50.2 ft. w/W nail & plate.

Reset - 1951-63 GLO brass cap, 1' under surface of rock
logging road.

N.70°W., 43.5' to most easterly point of large
boulder 15'x15'x20'.