

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; and 24 of T25-4

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - W. H. Byars, Contract #152 dated June 1871
(DCSO records, Volume 9 Page 3666)

Set 1/4 sec. post, from which
 A Maple 6" dia. bears N.75°W., 35 lks. dist.
 A Yew, 10" dia. bears N.70°E., 31 lks. dist.

Bureau of Land Management Dependent Resurvey, - Norman Price
Special Instructions dated April, 1940 - Survey, 1943
(DCSO records, Volume 27 Page 11523-24)

Point for orig. 1/4 sec. cor., determined by reference to the
record bearing and distance from the old NE bearing tree.
At point for corner, set an iron post, 3 ft. long 1" dia. 28"
in the ground, with brass cap mkd: 1/4

S24|S19
 1943 from which

A Yew 12" dia. bears N.70°E., 31 lks. dist. marked
 1/4 S B T. I re-blaze and re-mark this old BT
 1/4 S 19 B T.
An I. Cedar 14" dia. bears S.49 3/4°W., 24 lks. dist.
 mkd. 1/4 S 24 B T. (New BT)

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J.
Flause - 1/26/98 - C.S. File 64/79-10

Found - 2 1/2" dia., brass cap, properly marked, on a 1" O.D.
 by 36" long iron pipe is found bent and out
 of ground. 1943 BLM
10" now 27" dia., Yew with scribing visible "1/4 S19
 BT" on a open rescribed 13" southerly trunk
 of double trunked Yew. Center of root crown
 bears N.70°E., 20.5 ft. (Agrees w/rec.) OBT
14" now 23" dia., Cedar with a fully healed single
 blaze, bears S.43°W., 15.8 ft. (Rec. S.49
 3/4°W., 15.8 ft.) 1943 BLM
Reset - 1943 BLM BC/IP is straightened and reset at a
 position determined from BT's as noted above,
 protrudes 5" above ground. The marks "DCSO
 RESET 1998" are added to brass cap.
New BTs - 14" R. Cedar, double blazed and scribed "1/4 S24 CS
 BT" bears S.2°W., 29.9 ft.
 5" D. Fir, double blazed and scribed "1/4 S19 CS BT"
 bears S.70°E., 4.1 ft.

FD OK, K HOFFINE - 2/8/2007 - C.S. FILE 65/60-27

