

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Contract #52 dated June 1871
(DCSO records, Volume 9 Page 3756)

Set ¼ sec. post, from which
A Fir 14" dia. bears S.50°E., 8 lks. dist.
A Fir 18" dia. bears N.40°E., 36 lks. dist.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin
and Roseberry - Special Instructions dated July 8, 1957 and
July 15, 1958 (DCSO records, Volume 29 Page 12311)

Restored corner at record distances from orig. bearing trees:
A decayed and burned fir stump, 35" dia. bears N.41½°E.,
36" lks. dist. with no scribe marks visible on a
burned and rotten blaze. (Rec. bearing N.40°E.)
A Fir 29" dia. bears S.42°E., 8 lks. dist. with no
scribe marks visible on a burned & chopped out
blaze. (Record bearing S.50°E.)

At the corner point, set iron post 28" long 2½" dia. 26" in
the ground, with brass cap marked: T25S R4W

¼ S 19
S 30
1957 from which

A Fir 30" dia. bears N.7°W., 50 lks. dist. marked
¼ S19 BT.

A Fir 20" dia. bears S.21°W., 33 lks. dist. marked
¼ S30 BT.

Doug. Co. Surveyors Off. - Milo Godfrey; V. Tracy; M. Stone
Feb. 27, 1964 - C.S. File 53/47-20

Found - 1957 GLO brass cap.
22" Fir S.21°W., 21.8 ft. scribing visible, tree
alive and in good condition.
30" Fir N.7°W., 33.0 ft. uprooted and down.
New BT - 6" D.Fir S.33°E., 28.0 ft. mkd: ¼ S30 CS BT.
No suitable tree available north of line.

Bureau of Land Management dependent Resurvey - Jelley and
Rogers - Group #1084, Survey Jan/June 1982 (DCSO records,
Volume 45 Page 17525)

(Continued Next Page)

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Found - 1957 Cadastral brass cap.
A root hole, bears N.41½°E., 36 lks. dist., no tree remaining. (Orig. BT)
A sawed Fir stump 30" dia. bears S.42°E., 8 lks. dist., no marks visible. (Orig. BT)
A root hole bears N.7°W., 50 lks. dist. with an uprooted Fir alongside, 30" dia. with healed blaze. (1957 BT)
A Fir 30" dia. bears S.21°W., 33 lks. dist. with fragmentary scribe marks visible on opened blaze. (1957 BT)
A Fir 24" dia. bears S.33°E., 42½ lks. dist., with healed double blaze. (Godfrey BT)
New BT - A Fir 10" dia. bears N.56 3/4°E., 35 lks. dist. mkd: 1/4 S19 BT.

Douglas County Surveyors Office - Randall Smith & Stephen Flause - Aug. 7, 1997 - C.S. 64/75-31

Mon. Fd.- ¾ dia. Brass cap on an iron pipe found 2" below ground (1957)
Bt's Fd.- 14" now 24" dia. 2' high rotted D.fir stump we open and find scribing "BT", bears S.42°E., 5.3' (agree with latest rec.) OBT
Remains of rotted D.fir found at rec. Position of orig. NE BT "N.41½°E., 23.8'".
20" now 38" dia. D.Fir, with a previously opened unhealed blaze, no scribing visible, bears S.21°W., 21.8' 1957.
30" now 30" dia. down D.fir, with a fully healed single blaze, root hole agrees with rec. N.7°W., 33'. 1957.
24" now 18" dia. D.fir, with a fully healed double blaze, bears S.33°E., 28' (agrees with rec.) 1964.
10" now 12" dia. D.fir, with a fully healed single blaze, bears N.56 3/4°E., 23.1' (agrees with rec.) 1982.
New Accessories -
11" dia. D.fir double blazed and scribed "¼ S19 CS BT", bears N.2½°W., 17.3'.
Corner lies in an E-W fence line

