

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 057020

PRIMARY CORNER DESCRIPTION NW Cor. I. Smith DLC #57

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Addison R. Flint, Contract #28 dated April, 1854 ----- Set stone post 30 x 8 x 4. Raised mound with trench as per instructions.</p>
<p>Floyd C. Frear, Engineer - W. Paulen; Don Garret; Dale McWhorter; John Hess - March 10, 1955 - C.S. File 46/101 ----- Large rock at corner. We marked: 10" Forded B.Oak N.82°45'W., 70.8 ft. 14" B.Oak N.56°30'E., 47.0 ft. Both on edge of small creek.</p>
<p>James W. Byron; R. Irving; J.Fee - Sept. 12, 1955 C.S. File 46/126 ----- Found - 15"x6" stone, cross on top 24" above ground scribed T25S R6W (on stone) at base of 48" W.Oak. 12" Ash scribed N.W. Cor DLC 57 bears N.55¾°E., 47.01 ft. (B.Oak per Frear) 24" W.Oak scribed N.W. Cor. DLC 57 bears N.83¾°W., 71.5 ft. (B.Oak per Frear)</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - V. Tracy; M. Stone July 19, 1962 - C.S. File 49/123-5 ----- Found - 24" W.Oak N.83¾°W., 70.8 ft. scribing still visible not completely healed over. 12" Ash N.56½°E., 47.0 ft. scribing still visible. Scar not healed. Road has been widened. Corner rock not found. Corner falls in East edge of traveled portion of road as it is now. Drove 3/4" steel reinforcing rod at corner. BTs still in good condition.</p>
<p>Found OK, January 26, 1971, V. Tracy - C.S. File 49/123-125</p>
<p>Found 3/4" iron rod 9" under road surface, Sept. 1996; D. Edwards - M 125-74.</p>
<p> </p>