

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 6; & S. 1 of T25-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Wm. P. Heyden, Contract #656 dated May, 1896  
(DCSO records, Volume 9 Page 3852)

-----  
Set a Cedar post, 3 ft. lone, 4" square, 24" in the ground  
for 1/4 sec. cor. mkd. 1/4 S on N. face, from which

A Fir 24" dia. bears S.38°E., 64 lks. dist. mkd: 1/4  
S B T.

A Fir 24" dia. bears S.67°W., 109 lks. dist. mkd: 1/4  
S B T.

Milo E. Godfrey, Deputy Co. Surveyor; Vernon Tracy; Mike  
Stone - July 1963 - C.S. File 49/123-88

-----  
Found - 32" Fir S.57°W., (Not S.67°W.) 71.9 ft. Has been  
previously opened, scribing visible on old  
face. Tree alive & in good condition.

36" rotten Fir snag S.38°E., 42.2 ft. Scribe marks  
visible on portions of old faces. Part of "S"  
and part of "B".

Set brass cap at cor. mkd: County Surveyor's Office 1963  
T25S R7W W 1/4 S6 R6W

New BTs - 5" D.Fir S.27°E., 21.3 ft. mkd: 1/4 S6 CS BT.

5" D.Fir N.75°E., 12.1 ft. mkd: 1/4 S 6 CS BT.

Bureau of Land Management dependent resurvey - Lynn Roseberry  
July 20, 1967 to Sept. 25, 1968 - DCSO records, Vol. 36 Pg.  
14949

-----  
Found - DCSO brass cap.  
Orig. BT, a rotted fir stump, 36" dia. bears  
S.38°E., 64 lks. dist. with scribe marks S B  
visible on rotted blaze.

Orig. BT, a Fir, 32" dia. bears S.58 1/2°W., 109 lks.  
dist., with fragmentary scribe marks visible  
on open blaze. (Record, S.67°W.)

1963 BT, A Fir 6" dia. bears N.76°E., 32 1/2 lks. dist.  
with scribe marks 1/4 S6 CS BT visible on open  
double blaze.

1963 BT, A Fir 6" dia. bears S.26 1/4°E., 18 1/2 lks.  
dist. with scribe marks 1/4 S6 CS BT visible on  
open double blaze.

This monument is erroneously mkd. and is actually common to  
both secs. 1 and 6.

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & Sec. 1, T25-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Bruce Shaner Engineering - For: Wester Timber Company - July 28, 1989 - C.S. File 63/96 and RM 3-72

-----  
CORNER REPORT ONLY

Found - 1" Iron pipe with 2½" brass cap erroneously marked "County Surveyors Office W ¼ S6 T25S R6W R7W 1963", from which  
36" D.Fir now a rotten stump bears S.38°E., 42.2 ft.  
36" D.Fir, face overgrown bears S.58½°W., 71.9 ft.  
8" D.Fir face overgrown, bears N.76°E., 12.2 ft (BLM record 21.4 ft.)  
10" D.Fir, face overgrown, bears S.26¼°E., 21.4 ft. (BLM record 12.2 ft.)

Apparently there was a transcription in USBLM notes on above 2 trees' distances. Also, BLM notes say that the above corner erroneously mkd. & is actually common to both sections 1 & 6. Corner lies West approx. 80 ft. from the main road (dirt) along the top of Tye Mt. ridge.

DCSO-GIS Corner visitation - 7/7/2004 - Typed: 1/24/2011 - C.S. File 67/33-1

-----  
Monument - 1.25" BC/IP  
Comment - OK

Douglas Co. Surveyors Office - Stephen Flause & Jeff Lorsung - 11/5/2019 - C.S. File 67/46-9

-----  
Found OK  
Unrecorded RBG 10x60' Fir snag partially healed single blaze "BT", N.57°W., 24.3.  
Line tag on fir at edge of forest access Rd ≈ S.30°E., 50.0

Lat: 43.42397467  
Long: -123.4658312