

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9, Page 3823)

Set ¼ sec. post, from which
 A Y.Oak 20" dia. bears S.3½°W., 1024 lks. dist.
 A Maple 12" dia. bears S.72¼°E., 515 lks. dist.

Milo E. Godfrey, Deputy Co. Surveyor - V. Tracy - Aug. 8,
1963 C.S. file 49/123-104

Found - Old, rotten Oak snag S.3½°W., 675.8 ft. Has been
 chopped open previously & upper face
 completely rotted away. Cut open & found
 reverse scribing "BT".
 Two small Maple trees in immediate vicinity of
 location for SE BT, (12" Maple S.72¼°E., 515
 lks.) No stump hole nor any portion of orig.
 tree remains.
Set brass cap at cor. mkd: County Surveyor's Office, 1963
 T25S R6W ¼ S27|S26
New BT - 18" W.Oak S.45°E., 227.9 ft. mkd: ¼ S26 CS BT.
The power pole at the intersection of Hardin-Davis Hill Road
& DLC Line road bears S.54°W., 161.8 ft. No other trees near.

Douglas Co. Surveyors Office - V.R.T. - Jan. 26, 1971 - C.S.
File 49/123-125

Found BT & Power pole. Brass cap had been knocked out & reset
in wrong place - we straighten pipe & reset - also set 6'
marker pipe alongside,

Fd. OK by K.Degroot, May 1999 - M132-1

DCSO-GIS Corner visitation - 6/28/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - (needs) rehab