

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by - A.R. & S.C. Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 9 Page(s) 3947)

Set fir 1/4 sec. post 3 ft. long & 3" sq. from which
A fir, 10" dia., bears N.90°E., 21 lks.
A fir, 15" dia., bears S.50°W., 21 lks.

GL0 resurvey by Morris Wygant, Compassman for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3973-4)

Set a cedar post, 3 ft. long, 4" sq. 24" in the ground for 1/4 sec. cor. marked 1/4 S10 on W & 11 on E face from which
A burnt fir, 42" dia. bears S.47°E. 153 lks. mkd: 1/4 S11 BT
A burnt fir, 40" dia. bears S.26°W., 81 lks. mkd: 1/4 S10 BT
No trace of old 1/4 sec. cor. (See method of procedure). At this cor. I set off 23°17'N. on the dec. arc; & observe the sun on the meridian, at noon; the resulting lat is 43°25'N.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - Sept. 1967 - C.S. File 49/88-18

Found - Orig. 42" burnt fir snag, badly decayed, S.47°E., 101.0 ft. (slope) "1/4 S11" scribe visible.
Orig. 40" burnt fir, S.26°W., 53.5 ft., turned out, downhill approx. 75 ft., scribe marks "1/4 S10" visible on upside.

Note - We could not find any hole or roots to indicate exact spot where the orig. SW BT stood. From our present corner location, there is a small slide approx. 35' wide & 40' long. If we had set the corner another 20.2' level dist., making a total of 101.0 ft. level dist., we would be approx. 15' west of old blazed line. This would put SW orig. BT above slide area and we find no evidence of stump hole nor roots. The call on ridge top also would not fit the rec. dist.

Because we were unable to determined where SW BT stood, we measure to top of spur to north 2 chs. or 132' on old blazed line. This fixed the corner locus as being slope dist. from orig. BT to SE.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T25S R8W OFFICE 1967 1/4 S 10 | S 11

New BTs- 18" D.Fir S.31°W., 4.6 ft. mkd: 1/4 S10 CS BT.
12" D.Fir N.44°E., 2.6 ft. mkd: 1/4 S11 CS BT.

Note - This corner lies on steep, SE slope 132 ft. S of spur, sloping E.

cont.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gary Langlitz, Deputy - Frank Silagy - Wayne Rogers, BLM - April 9, 1979 - C.S. 60/24-21

Found - 1" IP established by V. Ray Tracy, DCSO in 1967, with brass cap marked as described & Tracy's BTs as follows:

An 18" now 20" D.Fir alive & in good condition bears S.31°W., 4.6 ft.

A 12" now 12" D.Fir alive & in good condition with well healed double blaze, bears N.44°E., 2.6 ft.

At this time: The BLM, Roseburg Dist. is conducting a survey which utilizes this corner. After considerable discussion & investigation at the corner location, we determine that the corner should be more correctly located at record bearing & horizontal dist. from the orig. SE BT which was identified & described by Tracy in 1967. This OBT is in substantially the same condition now as when recovered in 1967. WE BASE our determination on the following reasons:

1. In his use of topographic calls, Tracy does not use the creek calls (rec 2.60 chains South of the ¼ cor) Both Tracy's corner position & the rec. corner position as based on the orig. SE BT exceed the rec. dist. North of the creek.
2. The corner locality was severely burned prior to the 1911 retracement evidence by the fact that the 1911 BTs we noted as "burnt fir". The orig. SE BT & the remains of the orig. SW BT, also identified by Tracy show no signs of healing over the blaze. We find no mature timber for at least 300 ft. South of the corner & none for nearly the entire half mile north of the corner. We find no evidence of a blazed line.
3. The corner location is on a steep SE slope with a thin cover of rocky soil over bedrock. We cannot determine the extent or amount of slide activity in this area.

At this time: We witness the setting of a new corner monument at a location from which the orig. SE BT, previously noted, bears S.47°E., 101.0 ft. (Rec. measurements S.47°E., 101.0 ft.) The new monument is a 2½" galv. IP set flush in the ground & leaning easterly, with brass cap attached marked:

US DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT
 T25S R8W
 ¼
 S 10|S 11
 1979

from which new BTs were marked as follows:

continued next page

TOWNSHIP 25 RANGE 08 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 10" D.Fir, scribed "¼ S10 BT" on a single blaze bears S.69°W., 9.6 ft.
A 15" D.Fir, scribed "¼ S11 BT" on a single blaze bears N.83¼°E., 4.0 ft.
WE OBLITERATE the 1967 DCS0 monument & accessories as follows: We leave the monument in place & deface the markings "T25S R8W ¼ S10 S11". We completely remove the scribing from both of the 1967 BTs.
From the BLM brass cap, the 1967 DCS0 monument bears S.44°E., 18.1 ft.

BLM Dependent resurvey by James E. Jelley, Harvey E. Wofford Wayne L. Rogers, Cadastral Surveyors under Group #926 & 958 surveyed Aug. 1977/April 1979 - (DCS0 recs. Vol. 42 Page(s) 16442-3)

The ¼ sec. cor. of secs. 10 & 11, determined at rec. bearing & dist. from the remains of a BT mkd. by Wygant:
A burned fir snag, 44" dia., bears S.47°E., 153 lks. with scribe marks ¼ S11 visible on open blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T25S R8W
 ¼
 S 10|S 11
 1979

from which new BTs
A fir, 15" dia., bears N.83¼°E., 6 lks., mkd: ¼ S11 BT.
A fir, 10" dia., bears S.69¾°W., 14½ lks., mkd: ¼ S10 BT.

Fd. & used on BLM Dependent resurvey by Dale Bedell, Cadastral Surveyor, under Group #1487, surveyed May/Sept. 1989 - (DCS0 records Vol. 50 Page(s) 18871-2)