

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Marvin C. Ramsey - For: J.H. Baxter & Co. - Wit: J. D Kirklin & James Goodin - July 6-29, 1960 - C.S. File 51/116-1E

~~INTERSECTION WITH THE NORTH & SOUTH CENTER LINE.~~

~~SET - AN IRON PIPE 3' LONG 1 1/2" DIA., 28" IN THE GROUND, MKD: RS404, FROM WHICH~~

- ~~18" D.FIR BEARS N.47°E., 62 LKS., MKD: C 1/4 S26 RS404 BT~~
- ~~22" D.FIR BEARS S.47°E., 25 LKS., MKD: C 1/4 S26 RS404 BT~~
- ~~14" HEMLOCK BEARS S.24°W., 24 LKS. MKD: C 1/4 S26 RS404 BT~~
- ~~34" D.FIR BEARS N.60°W., 10 LKS., MKD: C 1/4 S26 RS404 BT~~

Per letter dated April 24, 1961 from the Douglas Co. Surveyor, Fred Darby, the Surveyors office had found West 1/4 corner established by Ramsey was in error.

Marvin C. Ramsey - Corrective survey - May 1961 - C.S. File 51/116-2A&B

Point for center 1/4 sec. cor. at the intersection with the North & South center line.

Set - An iron pipe 3 ft. long 1 1/2" dia., 28" in the ground, mkd. RS404, form which

- D.Fir 14" dia., bears N.49°E., 25 lks., mkd: C 1/4 S26 RS404 BT
- Hemlock 8" dia., bears S.63°E., 13 lks., mkd: C 1/4 S26 RS404 BT
- D.Fir 38" dia., bears S.18°W., 29 lks., mkd: C 1/4 S26 RS404 BT
- D.Fir 20" dia., bears N.16°W., 45 lks., mkd: C 1/4 S26 RS404 BT

The center 1/4 sec. cor. set by RS404 in July 1960 bears S.0°45'E., 33 lks., which I destroy.

Note - The corrected center 1/4 information was added to the corner renewal records 8/3/2006, the corrected information was previously over looked by this office. JC DCSO