

TOWNSHIP 26 RANGE 09 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4748)

Set hemlock post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd 1/4 S on W face, from which
A fir, 22" dia., bears S.85°W., 18 lks. mkd: 1/4 S BT
A fir, 33" dia., bears S.45°E., 37 lks., mkd: 1/4 S BT.

Weyerhaeuser reports received June 17, 1970 C.S. 55/155B-9

Date: 2/68
42" Fir S.75 1/2°E., 59.5'
44" Fir S.70 1/2°W., 54.0'
By Whom: Williams, Lester

Douglas Co. Surveyors Office - Gregory E. Quibell, Deputy - John Powell - Gary Langlitz (guest witness) - 5/27/1982 -- C.S. File 61/36-16

Condition report only (possible corner)

Found - Steel fence post with line crossing sign attached & tag which indicated that this is the cor. location. This sign is located approx. 1/2 way up a steep cut bank on the south side of a rock rd. The tag is from Weyerhaeuser Timber Co. (WTC)
From this location both orig. BTs would have been destroyed by road construction.
42" fir stump with "WTC" bearing tag which reads "T26S R9W S23 45.5 ft. N4°W to W 1/4"
64" fir stump with "WTC" bearing tag which reads "T26S R9W S22 54 ft. N70 1/2°E to E 1/4"
32" fir stump with "WTC" bearing tag which reads "T26S R9W S22 71.8 ft. S34°E to E 1/4".
Since I could find no orig. evidence and since found BT stumps are not of record, I DO NOT set a monument.