

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO records Vol. 11 Page(s) 4839)

Set a basalt stone 20x15x5", 15" in the ground for 1/4 sec. cor. mkd. 1/4 on N face, from which
 A fir, 14" dia., bears N.60°E., 46 lks., mkd: 1/4 S9 BT.
 A maple, 10" dia., bears S.22°W., 39 lks., mkd: 1/4 S16 BT.

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - Dec. 1969 - C.S. File 54/94-94

Found - 14" D.Fir, now 34" N.60°E., 30.4 ft shows good scar.
 10" Maple now 14" S.22°E., 23.9 ft. (rec. 25.7 ft.)
 open for scribing "4" "S" "B"
 Also 20x15x5 stone firmly set at 1/4 cor. could find no mks.
 Using stone 2 bearings & 1 dist. I renew:

Set - Brass cap at 1/4 cor mkd: COUNTY SURVEYORS T27S R1W
 OFFICE 1/4 S 9
 1969 S 16

New BT - 10" D.Fir S.9°E., 17.8 ft. scribed 1/4 S16 CS BT.

Douglas Co. Surveyors Office - Karen Reed - Stephen Clause - Shawn Means - May 28, 1980 - C.S. File 62/50-12

Referenced notes only

Found - 1 1/2"x36" IP protruding 1.1 ft above ground with brass cap (1969 County) properly marked.
 20"x15"x5" basalt stone 1.35 ft. south of cap, no marks found on stone. Cap set at corner position by Powell 1969.
 Orig. 14" D.Fir now a 30" dia., with healed single blaze, bears N.60°E., 30.4 ft. Due to discrepancy in orig. bearing of other orig. BT we open scar to find scribe "4"
 Orig. 10" Maple now 12" with previously opened blaze, visible scribe "S1 B" bears S.22°E., 23.2 ft. (rec 25.7 ft. S.22°W.) I believe orig. brg. to be in error due to scribe in other orig. BT at rec. brg. & dist. also face is directed N.22°W.
 10" D.Fir now 11" with partially healed double blaze visible scribe "1/4 16" bears S.9°E., 17.3 (rec. 17.8 ft.) 1969

Set - Left cap & stone in position. This corner lies on the northerly side of a proposed road, therefore we reference it with the following:
 continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs 9 & 16

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Set - PK nail 3.5 ft. above ground in a 21" dia., D.Fir bearing N.5°W., 89.2 ft. blaze & tag tree, no scribe
5/8"x30" I.Rod with alum cap stamped "B0 2" bearing N.5°W., 63.2 ft. 4.5" above ground.
PK nail 2.2 ft. above ground in a 12" dia., chinquapin bearing S.89°30'W., 74.9 ft. blaze & tag tree, no scribe.
5/8"x30" I.Rod with alum. cap stamped "B0 1" bearing S.89°30'W., 94.8 ft. flush with ground.
Angle between PK nails 84°48'30"
See sketch attached to notes in C.S. File.
Work done with Gurley transit, GN 0993

Douglas Co. Surveyors Office - Stephen J. Flause - Randall W. Smith - March 22, 1988 - C.S. File 62/50

Found - 1969 Co. Surveyor 2" dia. brass cap, properly mkd., on a 1 3/8" O.D. iron pipe protruding approx. 13" above ground.
A possible orig. corner stone measuring approx. 20x15x5" with no marks visible, is found loosely set on surface of ground approx. 1 ft south of brass cap monument.
Accessories measured from found brass cap
Orig. BT, a fir, 14" dia. now a 32" DBH D.Fir with a partially opened blaze revealing the scribing "4" bears N.60°E., 30.4 ft.
Orig. maple bearing tree removed by road work
A 10" D.Fir now a 13" DBH D.Fir with a fully healed double blaze bears S.11 1/2°E., 17.3 ft. (1969, S.09°E., 17.8 ft.)
Bearing objects from 1980 found as follows:
A PK nail 3.5 ft. above ground in a 21" dia. D.Fir now a 26" DBH D.Fir blazed but not scribed bears N.06 3/4°W., 89.2 ft. (Rec. N.05°W., 89.2 ft.)
A 5/8"x30" I.R. with alum, cap stamped "B0 2" protruding 2" above ground bears N.06 3/4°W., 63.2 ft. (rec. N.05°W., 63.2 ft.)
A PK nail 2.2 ft. above ground in a 12" diam. chinquapin now a 15" DBH chinquapin blazed but not scribed bears S.89 1/2°W., 74.9 ft.
A 5/8"x30" IR with alum, cap stamped "B0 1" approx. 3" under duff surface, bears S.89 1/2°W., 94.8 ft
Brass cap monument agrees well with accessories. Stone monument is left in found position as an accessory to B.C. Monument lies approx. 30 ft. North of spur logging road on moderately steep NW slope.

cont.

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley - For: Roseburg Forest Products - Sept. 1990 -
C.S. File 63/104-31

Found - 2" brass cap on an iron pipe found pulled out by
logging.

26" D.Fir N.6¾°W., 89.2 ft., now a stump.

Alum. cap on an iron rod stamped "B02" N.6¾°W.,
found at 62.3 ft. not 63.2 ft.

34" D.Fir N.60°E., 30.4 ft., now a stump. Orig BT.

13" D.Fir S.11½°E., 17.3 Ft. Now bent over stump.

15" Chinquapin S.89½°W., 74.9 ft. now a stump.

Aluminum cap on an iron rod stamped "B01" S.89½°W.,
94.8 ft

Set - Reset the county surveyors brass cap and iron pipe
in their proper location from the bearing trees.
No new BTs available, as area has recently been
clearcut.

Location - Just below toe of fill on forest service road.