

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 14 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5051)</p> <p>-----</p> <p>Set ¼ sec. post, from which A W.Oak 20" dia. bears S.28°W., 33 lks. dist. A W.Oak 22" dia. bears N.27°E., 24 lks. dist.</p>
<p>G.L.O. dependent resurvey by Elmer F. Strickler, Deputy Surveyor under Special Instructions dated Jan. 22, 1917 (DCSO records, Volume 12 Pages 5088-89)</p> <p>-----</p> <p>After careful and diligent search, am unable to find any trace of old ¼ corner. Set a basalt stone, 14 x 7 x 5", 10" in the ground, for ¼ sec. cor. of sec. 14 only, marked ¼ on W. face, from which: A B.Oak 20" dia. bears S.75°30'W., 124 lks. dist. mkd. ¼ S 14 BT. A Fir 28" dia. bears N.7°30'W., 227 lks. dist. marked ¼ S 14 BT.</p>
<p>James W. Byron, Deputy Co. Surveyor - Milo Godfrey; S.A. Bilow - Dec. 31, 1958 - C.S. File 49/130-8 &amp; 9</p> <p>-----</p> <p>Found - Stone at corner and drove ¾" Rod alongside rock, which is badly broken up. 20" B.Oak S.75½°W., 81.8 ft. (should be S.77°W. 83.8 ft.), now 28", shows good scar. I do not open. Large Fir stump hole checks bearing and distance for NW. BT. New BT - 9" B.Oak bears N.41°W., 49.4 ft. scribed ¼ S14 CS BT. (Sketch in C.S. File)</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Stone, Darby and Halterman - Oct. 1963 - C.S. File 53/33-15</p> <p>-----</p> <p>Found - ¾" re-enforcing rod driven nearly flush with ground. 27" B.Oak S.77°W., 83.8 ft. shows scars. Alive and in good condition. 9" B.Oak N.41°W., 49.4 ft. is burned and dead, scribing visible. New BT - 11" B.Oak N.61°W., 194.8 ft. mkd: ¼ S14 CS BT.</p>
<p>Found OK, Burton Holt, March 1982, M 91-37</p> <p>BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1925, surveyed June/Dec. 2000 - (DCSO rec. Vol. 53 Page(s) 20547-8)</p>