

PRIMARY CORNER DESCRIPTION N.E. COR. DLC #49

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Addison R. Flint Contract #28 Commenced July 1854 ----- Set - Post from which A W. Oak 10" dia. bears S.79°W., 291 lks. Raised mound with trench as per instructions.</p>
<p>A. Boyer, Douglas Co. Surveyor - Wit. N.E. Richardson; Harvey Eppstein, Jr.; Fred Fisher - Nov. 23, 1938 - Vo. 4 Pg. 54 ----- Iron Pipe ½" x 36" Black Oak 15" dia. bears S.84°E., 11.3 ft. marked Cl. 49 C.S. B.T. White Oak 8" dia. bears S.27°W., 30.0 ft. marked Cl. 49 C.S. B.T.</p>
<p>Douglas County Surveyor's Office - Byron &amp; Godfrey, Deputies Nov. 21, 1963 - C.S. 53/38-7 ----- Found - ½" I.P. (bent over) set by Boyer in 1938. Straightened pipe. Stump of 15" B. Oak S.84°E., 11.3 ft., opened &amp; found scribing "BT". Stump of 8" W. Oak S.27°W., 30.0 ft. shows good scar. Did not open. No trace of original bearing tree. New BTs - 9" W.Oak S.22°E., 58.0 ft. mkd. NE DLC 49 CS BT. 9" W.Oak N.49°E., 101.0 ft. mkd. NE DLC 49 CS BT.</p>
<p>Doug. County Surveyors Office - Randall W. Smith &amp; Stephen J. Flause. Mar. 18, 1993 - C.S. File 64/41-7 ----- Found - ½" I.D. Iron Pipe, protruding 2" above ground. (1938 Boyer renewal) Accessories Found - 15" now 14" dia. 1½ ft. high rotted Oak stump. No blazes or scribing visible. Bears S.84°E., 11.3' (agrees with rec.) 1938 Boyer renewal. 8" W.Oak now depression bears S.27°W. 30.0' (agrees with rec.) 1938 Boyer renewal. 9" dia. now 14" W.Oak with a fully healed double blaze. Bears S.22°E., 58.0' (agrees with rec.) 1963 Byron renewal. 9" dia. now 14" W.Oak with a fully healed double blaze bears N.49°E., 101.0' (agrees with rec.) 1963 Byron renewal.</p> <p>continued next page</p>

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 049010

PRIMARY CORNER DESCRIPTION N.E. COR. DLC #49

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BT not recorded in 1963 Byron renewal, in CS 53/38,  
BT lined out with note "to be cut" 24" dia.  
now 49" W.Oak with a fully healed double blaze  
bears N.62°E., 78.7' (rec. CS 53/38 N.61°E.,  
78.7') 1963 Byron renewal.

Monument Set -  
Unable to set BC/IP, water at ground level. Will set  
BC/IP at a later date.

New Accessories -  
3/4" I.R. bears S.75°E., 200.33' (I.R. at fence  
corner of N-S and W. running fence lines.