

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 050050

PRIMARY CORNER DESCRIPTION SW Cor Morgan DCI #50

Alias 042060 Description ESE Cor. Finch DLC #42
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint Contract #28 dated July, 1854

Set post in prairie, deposited stone 6 x 4. Raised mound with trench as per instructions.

Ben B. Irving, County Surveyor - For California Oregon Power Co. - April, 1953 - C.S. 45/150

Set - 3/4" iron rod, from which
The SW corner of the Dixonville Store bears N.46°21'E., 57.33 ft.
The NW corner of Dixonville Sub Property bears S.25°16'E., 41.26 ft.
The SE corner of the E.E. Hatfield Blacksmith Shop bears N.36°52'W., 50.45 ft.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 11/18/93 - C.S. File # 64/50-13

Corner lies at the intersection of paved roads. A strong metal signal was noted at the approx. position of the corner.
Found - One tie from 1953 BBI renewal remains, a 1/4' dia., copper rod set in concrete, bears S.25°16'E., 41.26' (Agrees well with 1953 BBI ren. & recent surveys)

New Accessories - **BEARINGS ARE TRUE**
DCSO BC in conc. mon. "Dixie 1980" bears S.71°56'36"W., 100.08'.
DCSO BC in conc. mon "Dixie RM1 1980" Bears N.69°57'23"W. 96.44'.
OGS BC in conc. mon. "S83F253 1934" bears S.20°48'13"E., 45.13'.
5/8" I.R. bears N47°34'28"E., 43.04'.
5/8" I.R. bears N.61°34'04"E., 60.95'.
See sketch in file.

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 4/7/2008 - C.S. File 67/25-40

Fd. Ok as per DCSO 1993 rec.