

PRIMARY CORNER DESCRIPTION MC Cor. W. bdy. Sec. 19 Left Bank

Alias 836010 Description M.C. Left Bank, So Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder and Guile - 1853

Over River by triangulation and set meander post, from which
A Willow, 8" dia. bears S.72½°W., 12 lks. dist.
A Willow, 6" dia. bears N.75°E., 12 lks. dist.
Course of River NE and SW, curving to the East and West.

A Boyer, Deputy Co. Surveyor - Wit. N.E. Richardson and P.D. Woford - Sept. 27, 1936 - Vol. 4 Pg. 51

Set - On Elks Island 3" x 3" red cedar post and 3/4" Iron bolt 30" long.
From which - A Balm of Gilead 20" dia. bears S.6¼°W., 39.8'.
A Balm of Gilead 15" dia. bears N.50°W. 30.5 ft. mkd. T.27S. R5-6 S14 S24.
(Searched for not fd. June 17, 1966 - C.S. 53/38 V.R.T.)

Douglas County Surveyors Office - John M. Powell, Frank Jones; Terry Connell - Aug. 22, 1966 - C.S. 53/38-9

Found No trace of iron bolt.
20" Balm, now 33" S.6½°W., 39.8 ft. (find dist. to be 41.2 ft.)
15" Balm, now 19" N.50°W., 30.5 ft. opened for "S" scribe.
Set - Brass cap at M.C. mkd.:
County Surveyor's Office, 1966 T 27 S R 6 S 24 S 19 R 5 W
New Bt - 25" Balm, N.43½°E., 31.5 ft. scribed MC S24 CS BT.

Douglas County Surveyors Office - R.W. Smith; S.J. Flause Aug. 24, 1987 - C.S. 62/45-16

Found - Doug. Co. BC on I.P. 2P ft. below surface of ground.
15" dia. Balm of Gilead now a 30" dia. down cottonwood tree with a rotted out blaze bears N.50°W., 30.5 ft. to stump hole. (agrees well with record).
Southwest BT gone.
25" dia. Balm now a 28" dia. cottonwood tree with a fully healed double blaze bears N.43¼°W., 30.8 ft. (Rec. N.43½°W., 31.5 ft.)
Set - A 5/8" x 30" iron rod with DCSO alum. cap set plumb over DCSO BC. I.Rod protrudes 3" above ground mkd. "Douglas Co. Surveyor".

(CONT. NEXT PAGE)

PRIMARY CORNER DESCRIPTION MC Cor. W. bdy. Sec. 19 Left Bank

Alias 836010 Description M.C. Left Bank, So Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New BTs - 10" locust double blazed and scribed "MC S24 CS BT"
bears N.76½W., 15.0 ft.
9" Ash double blazed and scribed "MC S19 CS BT"
bears S.33°E., 7.1 ft.
6" Maple double blazed and scribed "MC S19 CS BT"
bears N.15°E., 59.9 ft.
Near South end of Elk Island in Roseburg approx. 50 ft. North
of high water bank.

Douglas Co. Surveyors Office - Stephen J. Flause - 11/4/2006
- C.S. File 67/14-42

Found - No previously noted monuments are found. Island has
flooded several times since last renewal &
sandy soil has been washed away or been
deposited in many spots.

Thoroughly examined area with metal detector & fd.
no indication of set monuments at, or near,
position referenced by fd. BTs.

No orig. BTs fd.

From 1966 renewal possible evidence of then new 25"
dia., Balm, now a 30+", fallen & washed out of
position cottonwood with a partially shattered
base, no scribing or blaze evident and location
of root hole is not definitive.

From 1987 renewal, evidence of the 3 new BTs fd.

10" locust now a 12" DBH locust with a partially
healed double blaze scribed as recorded bears
N.76½°W., 15.0 ft. (as per rec.)

9" Ash now a 10" DBH Ash with a partially healed
double showing illegible partial scribing on
rotted faces, fallen & out of ground near root
hole. Hole bears S.33°E., 7.1 ft. (as per rec.)

6" Maple now a 12" DBH Maple with a fully healed
double blaze bears N.15°E. 59.9 ft (as per rec)

New - At the position indicated by the fd. BTs is set a
5/8" dia., 5 ft. long iron rod with a 1½" dia.,
alum. cap, the top of which is approx. flush
with the ground surface. Cap mkd:

DOUGLAS CO. SURVEYOR

M C

S 24|S 19

2006

Several smaller locust & maple trees are nearer
monument than new BTs but these trees are
severely pistol-butt or are leaning with a
deeply buried root crown. cont. next page

PRIMARY CORNER DESCRIPTION MC Cor. W bdy Sec 19 Left Bank

Alias 836010 Description M.C. Left Bank, So Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

15" DBH, locust scribed "MC S19 CS BT" on a double blaze bears N.71 $\frac{3}{4}$ °E., 65.5 ft.
13" DBH, locust scribed "MC S24 CS BT" on a double blaze bears N.33 $\frac{1}{2}$ °W., 58.7 ft.
Note - Monument is in very sandy, often eroded soil at south end of Elk Island. Monument could be deeply covered or washed away in next flood event. Compass decl. 16 $\frac{1}{2}$ °E.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Oct. 24, 2011 - C.S. File 67/33-44

Found - A 2 $\frac{1}{2}$ " dia., Brass cap (properly mkd) on a 1" I.D. iron pipe is firmly set approximately 2" below surface of newly built dirt road. 1966
Road construction has removed, in the least, 2 ft. of the silt previously noted as deposited in area in 2006 renewal. A search was made but no evidence of the 1987 or 2006 iron rod monuments was found.
No OBTs fd.
No 1936 BTs fd.
No good evidence of 1966 BTs fd. (some out of position large Balm trunks with no discernible root holes)
A 10" Locust now a 12" DBH Locust with a partially healed double blazes showing the scribing "MC S24 CS" "BT" bears N.76 $\frac{1}{2}$ °W. 15.0 ft (as per rec) 1966
Near bearing and dist. of SE Ash tree is a possible root hole. 1966
A 6" maple, now a 13" DBH Maple with a fully healed double blaze; bears N.15°E., 59.9 ft. (as per rec) 1966
A 15" DBH Locust (still same) with a partially healed double blaze show the scribing "MC S19 CS" "BT"; bears N.71 $\frac{3}{4}$ °E., 65.5 ft. (as per rec.) 2006
A 13" DBH Locust now a 14" DBH Locust with a partially healed double blaze showing the scribing "MC S24 CS" "BT"; bears N.33 $\frac{1}{2}$ °W., 58.7 ft. (as per rec) 2006
New - A metal witness post & sign is set 1 ft. south of BC monument.
Compass decl. 15 $\frac{3}{4}$ °E.

PRIMARY CORNER DESCRIPTION MC Cor. W bdy Sec 19 Left Bank

Alias 836010 Description M.C. Left Bank, So Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch
- 11/7/2013 - C.S. File 67/40-20

Found - Brass cap/iron pipe monument as described in 1966 renewal and noted as fd in the 1987 and 2011 renewals is now washed out of position by flooding. Monument is buried under 2 ft. of silt, 10+ ft. NE from corner position.

The metal witness post and sign is also washed from its 2011 position and is now buried under silt a few foot farther down-stream from the fd. BC.

Two 2011 BTs are washed out of position by flooding and 2 remain standing:

The NW'ly 10" locust and NE'ly 15" locust are fallen and washed several ft. down-stream; their root-crown positions are both entirely washed away and cannot be determined.

The NE 13" DBH Maple and NW 14" DBH locust are fd as described.

New - Monument position is in unstable ground and is subject to future flooding. Monument could be set in future if erosion uncovers bedrock.

Using the two fd BTs, a position is determined that would be 50 ft. north from the meander corner location. This position is S.63¼°W., 17.4 ft. from the 13" maple BT and N.88¼°E., 32.4 ft. from the 14" locust BT. Measuring a distance-distance intersect from the two fd BTs the point 50 ft., north from the meander corner is established and at this point is set a 5/8"x5 ft. long iron rod protruding 6" above ground.

A metal witness post and sign is set 1 ft., south from the set 5/8" iron rod.

Note - Corner is on south end of Elk Island. Erosion continues.

Compass decl. 15½°E.