

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
 A Y.Oak 12" dia. bears S.78½°W., 56 lks. dist.
 A Y.Oak 14" dia. bears N.65°E., 80 lks. dist.

James W. Byron, Deputy County Surveyor - Milo Godfrey;
Clete Putnam - January, 1961 - C.S. File 49/79-6

Found - Both orig. BTs. Each BT, now down 7 badly rotted.
We find old axed face & possible reverse scribe
marks at S.W. BT.
BTs check record bearings & distances.
Also find pointed 18"x6"x10" corner stone. (See
Vol. 1 Page 242)
New BTs - 12" B.Oak, N.33°E., 24.7 ft. scribed ¼ S19 CS BT.
6" W.Oak, S.59°W., 13.6 ft. scribed ¼ S30 CS BT.
(See C.S. file for sketch of fences)

Doug. County Surveyors Office - Randall Smith, Deputy - S.J.
Flause - May 4, 1993 - C.S. File 64/43-14

Found - 1961 2½" dia. Brass cap on a 1½" O.D. I. Pipe, pro-
truding 14" above ground. (1961 Byron cap, not
recorded in previous typed renewal, is in C.S.
File 49/79) Corner stone top measures 6" x 6"
x 6" above ground along North edge of BC/IP.
(See Vol. 1 Page 242)
12" now 17" dia. B.Oak with a fully healed double
blaze bears N.33°E., 24.7 ft. (agrees w/rec.)
1961 Byron.
6" now 7" dia. W.Oak with a fully healed double
blaze, bears S.59°W., 13.6 ft. (agrees w/rec.)
1961 Byron
Possible rotted remains of down orig. SW BT found
near record bearing and dist.
All remains of orig. NE BT now gone.
New BTs - 8" dia. D.Fir double blazed "¼ S19 CS BT" bears
N.15½°E., 7.4 ft.
12" dia. Madrone bark scribed "¼ S30 CS BT" bears
S.44¼°E., 20.8 ft.
Corner lies at the intersection of a North and East running
fence lines.

Fd. OK - D.Bentz - June 1996 - Vol. 19 Pg. 9 A-K
Fd BC - N Hibbs - 12/2019 - M171-75