

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 & 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set post cor. to Secs. 1, 2, 11 and 12 from which  
    A Y.Oak, 13" dia. bears N.22½°E., 34 lks. dist.  
    A Y.Oak, 30" dia. bears S.60°W., 104 lks. dist.  
    A W.Oak, 18" dia. bears N.88½°W., 137 lks. dist.  
No tree near in Sec. 12.

N.E. Richardson, Deputy Surveyor - A.R. Evans; M.R. Godfrey  
September 2, 1948 (could not find source)  
-----

Set 1" I.P. with brass cap mkd. County Surveyor's Office  
from which:  
    5" Laurel bears S.55°E., 9.6 ft.  
    9" B.Oak bears S.57°W., 40.5 ft.  
Corner was identified by three O.B.T's which were left, one  
being just a identify.

Doug. Co. Surveyors Office - L.E. Monrean; Mike Cline  
August 10, 1977 - C.S. File 59/38-13  
-----

Found - A 1" I.P. with brass cap mkd. "County Surveyors  
          office" T27S S2 S1 S11 S12 R6W.  
          An orig. B.Oak, 13" now 30" bears N.22½°E., 24.2 ft.  
          (Rec. Y.Oak at 22.4 ft.). We open & find old ax  
          marks, no scribing, center decayed.  
          A Y.Oak now a burned stump bears S.62°W., 66.9 ft.  
          (Rec. S.60°W., 68.6 ft.) No scribing found.  
          A 18" Y.Oak now 36" bears N.85°W., 90.4 ft. (Rec.  
          N.88½°W.) Tree has faint blaze.  
          A 5" now 7" Madrone bears S.55°E., to face S.59°E.  
          to center at base 9.6 ft. Tree has rotted  
          blaze "BT" visible.  
          A 9" now 13" R.Oak bears S.57°W., 40.5 ft. Tree has  
          well healed double blaze.  
New BTs - A 6" B.Oak bears S.72°E., 19.1 ft. Tree double  
          blazed & scribed "T27S R6W S12 CS BT".  
          A 9" B.Oak bears N.84°E., 20.0 ft. Tree double  
          blazed & scribed "T27S R6W S1 CS BT"

cont. next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Bruce Shaner LS #430 - July 16, 1982 - C.S. File 58/229-17  
-----

CORNER REPORT ONLY

On July 16, 1982, I tied into the above section corner &  
Found - A 1" I.P. with a 2½" DCSO brass cap properly mkd.  
32" B.Oak, orig. BT, with rotted out face, bears  
N.22½°E., 24.2 ft.  
Oak stump, orig. BT, now burned & rotted, bears  
S.62°W., 66.9 ft.  
36" W.Oak, Orig. BT, with healed over face, bears  
N.85°W., 90.4 ft. to face.  
8" Madrone BT with rotted face bears S.55°E., 9.6.  
14" B.Oak BT with healed over face, bears S.57°W.,  
40.5 ft.  
6" B.Oak BT scribes visible, bears S.72°E., 19.1 ft.  
10" B.Oak BT, scribes visible bears N.74°E., 20.0 ft  
(Rec. per 1977 Co. visit is N.84°E.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy  
R.W. Smith - Oct. 17, 1986 - C.S. File 62/38-6  
-----

Found - No monument of record was located. The location of  
the corner as determined by reference falls  
in a steep cut bank along northerly edge of  
new road. This area has been riprapped but  
still appears to be unstable.

A 32" now 36" dia. B.Oak with previously opened  
rotted blaze bears N.22½°E., 24.2 ft. (orig.)  
36" W.Oak with faint blaze visible bears N.85°W.,  
90.4 ft. to face.

All other BTs as reported in previous renewals have  
been destroyed.

No monument set. I believe this area is not stable enough to  
set monument.

New Accessories:

Chisled "X" in NNW corner of concrete pad of utility box  
bears N.87°E., 50.16 ft.

Set ½" x 8" spike mkd. "B01" in center of road bears  
S.22½°E., 41.5 ft.

Set ½" x 8" spike mkd. "B02" in center of road bears  
S.27½°W., 66.71 ft.

Bearings taken with staff compass. Dists. were measured with  
steel tape to nearest 1/100 ft. Dists. shown are horizontal.

Found OK by J. Estabrook, Jan. 2004 - M144-16