

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set $\frac{1}{4}$ Sec. post, from which
 A Y.Oak, 15" dia. bears S.13°E., 17 lks. dist.
 A Y.Oak, 26" dia. bears N.33°E., 34 lks. dist.

James W. Byron; M. Godfrey; S. Bilow - Jan. 3, 1958
C.S. File 49/61

No trace of original BTs can be found.
Set - Brass cap at corner mkd. $\frac{1}{4}$ S 24 S 25 T27S, R6W,
County Surveyor's Office, 1958.
From which - Bearing object chisled cross in concrete near
East end of concrete curb, bears N.28°E.,
9.0 ft.
18" W.Oak bears S.41°E., 6.0 ft. scribed $\frac{1}{4}$ S25
CS BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 11/9/93 - C.S. File 64/50-17

Found - $2\frac{1}{2}$ " dia., DCSO Brass cap on a $1\frac{1}{4}$ " O.D. Iron Pipe,
protruding 3" above ground. (1958 Byron).
Chiseled 2" "+" in a concrete curb, bears N.28°E.,
9.0' (Agrees with rec.) 1958 Byron.
18" W.Oak, bearing S.41°E., 6.0' from 1958 Byron
renewal is gone.

New Accessories -
Northeast corner of house at 1703 Kendall St., bears
S.4 $\frac{1}{2}$ °E., 20.9'.
Northeast corner of a 10 $\frac{1}{2}$ 'x16' concrete slab, bears
S.67 $\frac{1}{2}$ °W., 17.0'.
Southwest corner of the Southwest carport support
post at 1683 Kendall St., bears N.41°E., 62.0'.
See sketch in file.

Note - Corner lies approx. 170' East of the centerline of
Kendall St., between properties at 1703 and
1683, 1' North of a East-West fence.