

PRIMARY CORNER DESCRIPTION Meander Cor. E. Bdy. Sec. 13

Alias 838580 Description M.C. Left Bank, So Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Elder & Gile, Contract #31 dated April, 1853 ----- Intersect right left bank of Umpqua River, course E. and W. Set - Meander Post from which: An Ash, 5" dia. bears N.12½°W., 14 lks. dist. A Balm Gilead, 14" dia. bears S.82½°E., 138 lks. dist.</p>
<p>H.L. Eppstein; A. Boyer; N.E. Richardson - Sept. 27, 1936 Vol. 4 Pg. 51 ----- On Elks Island 3"x3" cedar post and 3/4" iron rod 24" long from which: Ash, 6" dia. bark blaze bears S.38°E., 23.8 ft. Ash, 6" dia. bark blazed bears S.87°W., 21.6 ft. marked C.S.M.C. S.13-18 BT.</p>
<p>Searched for, not found, June 17, 1966 V.R.T.; C.S. 53/38-13 Searched for, not found, 8/25/87, C.S. 62/45-14; L.E.M.</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Nov. 16, 2011 - C.S. File 67/36-1 ----- Reported as not found. Found - A 3/4x24" iron rod showing evidence of having once been driven into ground. This rod is now severely bent and lying on its side approximately 2" below surface. No trees of right age in vicinity. Position of fd. iron rod in relation to section corner just to the south is checked using a staff compass and an EDM. this measurement to be approximately 6 ft. North and 7 ft. East of the position of meander corner set in 1936. A survey would be required to reestablish this corner. Note - Found I.R. is near NW tip of Elk Island in area subject to much flooding and brush clearing in the last 75 years. Compass decl. 16½°E.</p>
<p>1</p>