

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 046040

PRIMARY CORNER DESCRIPTION SE Cor. Culver DLC #46

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Survey by J.A. Burnett, under Contract dated June 8, 1857

Set post, from which
A W.Oak 14" dia., bears N.5°W., 1842 lks.

Herbert L. Northcraft, For: Sanders - April 1971, M 42-24

Reset 5/8" x 30" Iron bar for DLC corner.
Did not find 1" x 1/2" I.Bar. (See M 33-44)
Original by Hix, 1914.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 10/22/2002 - C.S. File 66/34-38

Condition report
Found - 5/8" iron rod flush with ground 1 ft. East of a new
fence corner. Fence lines run N-S+W from
corner.
Fd. two 5/8" 0.2 ft. apart North 115 +/- at fence
corner. Fence lines run N-S+E. (Rec. North
115.1 ft.)
History - 1914 Iron pin (M33-41)
1968 Fd. Iron bar (M33-44)
1971 1"x1 1/2" iron bar not found, set 5/8"x30" I.R.
M42-24 & M46-63)