

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5784)

-----  
Set ¼ sec. post, from which  
A Cedar 18" dia., bears N.35°E., 21 lks.  
A Hemlock 6" dia., bears S.10°E., 31 lks.

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12864)

-----  
The standard ¼ sec. cor. of sec. 5, determined at record bearing and distance from the original SE. bearing tree:

A Hemlock 18" dia., bears S.10°E., 31 lks. dist. mkd. BT on opened face.

The orig. NE. bearing tree, a Cedar 30" dia., mkd. with open face, is dead and lying downhill to the NE., with original position lost.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap mkd:

-----  
¼ S 5  
T 28 S R 8 W  
S C  
1961

from which new bearing trees:

A Hemlock 24" dia., bears S.65°E., 57 lks. dist. mkd. ¼ S5 SC BT.

A Cedar 50" dia., bears S.83°W., 19 lks. dist. mkd. ¼ S5 SC BT.

A Bureau of Land management approximate corner point, number 404, mkd. with 2' iron pipe, protruding 18" above ground, bears S.35°W., 2 lks. dist.

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - S.J. Flause; Jean Holder; Vicki Woodral, crew - Aug. 30, 1977 - C.S. File 59/38-22

-----  
Found - 2½" I.P. loosely set extending 15" above ground with brass cap attached as described in the official BLM record of the 1961 resurvey.

This corner is located in a logged area. We find discrepancies in the measurements to the corner accessories from the present position of the monument. Also, we do not find the mound of stone put in place in 1961. BLM approx.

(Cont. Next Page)

TOWNSHIP 27½ RANGE 08 POINT IDENTIFIER # 239100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 5 only, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

corner point #404, a 2" I.P. was not found. We therefore conclude that this monument has been disturbed and proceed to reset it at the position as indicated in the official record.

Found - Probable remains of the SE. bearing tree, now a shattered Hemlock stump, size indeterminate, bears S.10°E., 20.5 ft., no markings found.

24" Hemlock stump with well healed blaze, bears S.65°E., 37.6 ft.

46" Red Cedar stump with scribing "¼ S5 SC BT" visible on partially healed blaze, bears S.83°W., 12.5 ft.

We RESET the 2½" x 28" I.P., 24" in the ground on a steep North slope with brass cap mkd. as described in the official record. We ADD markings "RESET 1977."

No new accessories.

Set fence post with survey marker witness sign attached, one foot East of the corner.

Fd. OK, Dec. 1986 by R. Hintz - M 103-8