

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5636)

Marked Fir tree, 30" dia., for 1/4 sec. cor., from which
 Fir 30" dia., bears N.45°E., 8 lks.
 Fir 24" dia., bears S.45°W., 7 lks.

BLM resurvey by Lynn M. Roseberry, under Group #636. Survey, May/June 1967 - (DCSO records, Vol. 34 Pages 14195-96)

The orig. 1/4 sec. cor., occupied by the remains of the orig. corner tree, a sawed and rotted Fir stump, 32" dia., with no marks remaining; from which the orig. bearing trees:

- A sawed and rotted Fir stump 30" dia., bears N.45°E., 10 1/2 lks. dist., with no marks remaining. (Rec. 8 lks.)
- A burned and rotted Fir stump 24" dia., bears S.45°W., 10 lks. dist., with no marks remaining. (Rec. 7 lks.)

At the corner point

Drive an iron post, 24 ins. long, 1 in. diam., 23 ins. in the center of the stump of the corner tree, with brass cap mkd:

T 28 S R 4 W
 1/4
 S 5 S 4
 1967

from which new bearing trees:

- A Fir 17" dia., bears S.88°E., 56 1/2 lks. dist., mkd. 1/4 S4 BT.
- A Fir 12" dia., bears N.29°W., 50 1/2 lks. dist., mkd. 1/4 S5 BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/14/2000 - C.S. File 66/14-26

Found - 1" O.D. iron pipe with 1967 BLM brass cap driven into center of rotted orig. corner tree.

30" now rotted D.Fir stump bears N.45°E. 6.9 ft. OBT
24" now rotted remains of a D.Fir stump bears S.45°W., 6.6 ft.

17" now 22" dia., D.Fir with a fully healed single blaze bears N.88°E. 37.3 ft. (BT tag agrees w/us)

12" now 22" dia., D.Fir with a fully healed single blaze bears N.27°W., (Rec. N.29°W., 33.3') 1967

New BTs- 10" dia., D.Fir double blazed & scribed "1/4 S4 CS BT" bears N.45°E., 4.0 ft.

7" dia., D.Fir double blazed & scribed "1/4 S5 CS BT" bears S.54°W., 7.6 ft.

Fence line run north + east from corner.

